

Date and Time: 8/26/14	Northing / Lat: 3028208.7
River: SUSITNA	Easting / Long: 1620635.6
X-Sec / PRM: 97.9	Bank Height (ft): 3.9' above WSE
Field Book #: -	Failure Mode: cantilever
Sampled By: MDH, BT, RV	Root Depth (ft): 3'
Comments:	Bank Angle (deg): vertical
Sample Number: S1	

LR-1

Bank Samples

2 SAMPLES → S1A + S1B

Younger surface ~ YFP / VB	Recent sand deposition on
Alders ~ 20'	Entire bank eroding - undercut
Poplars < 0.5' ø	↳ roots holding bank in place

