WETLAND DETERMINATION DATA FORM - Alaska Region

Project/Site: Susitna-Watana Hydroelectric Project	Borough/City:	Denali Borough	Sampling Date: 06-Aug-12
Applicant/Owner: Alaska Energy Authority		Samplin	g Point: SW12_T04_06
Investigator(s): CTS, EKJ	Landform (hills	ide, terrace, hummocks etc.):	Toeslope
Local relief (concave, convex, none): flat	Slope: 57.7	% / 30.0 ° Elevation: 831	
Subregion : Interior Alaska Mountains	Lat.: 63.4550399074	Long.: -148.6609199	Datum: WGS84
Soil Map Unit Name:		NWI classif	ication: Upland
	e of year? Yes (nificantly disturbed? curally problematic?	 No O (If no, explain in Are "Normal Circumstances" (If needed, explain any answer 	present? Yes 🔍 No 🔾
SUMMARY OF FINDINGS - Attach site map showin	ng sampling point l	ocations, transects, import	ant features, etc.
Hydrophytic Vegetation Present? Yes 🔍 No 🔿			

Remarks: N slope of esker is lush Sdet w lots of herbs, near toeslope, shoulder slope above is Stcb and flats below are Stcbw

VEGETATION - Use scientific names of plants. List all species in the plot.

	Absolute	Dominant	Indicator	Dominance Test worksheet:
Tree Stratum	% Cover	Species?	Status	Number of Dominant Species
1.	0			That are OBL, FACW, or FAC: (A)
2.	0			Total Number of Dominant
				Species Across All Strata: <u>3</u> (B)
3				Percent of dominant Species
4	0			That Are OBL, FACW, or FAC: <u>66.7%</u> (A/B)
5	0			Prevalence Index worksheet:
Total Cove	r:			Total % Cover of: Multiply by:
Sapling/Shrub Stratum 50% of Total Cover:	0 20%	of Total Cover:	0	OBL Species x 1 =
1. Vaccinium uliginosum	30	\checkmark	FAC	FACW Species x 2 =4
2. Empetrum nigrum	15	\checkmark	FAC	FAC Species <u>68</u> x 3 = <u>204</u>
3. Spiraea stevenii	10		FACU	FACU Species 62.1 x 4 = 248.4
1 Detulo nono			FAC	UPL Species $0 \times 5 = 0$
 Dasiphora fruticosa 	1		FAC	$\begin{array}{c} \hline \\ \hline $
	0.1		FACU	Column Totals: <u>132.1</u> (A) <u>456.4</u> (B)
6. Loiseleuna procumbens 7.				Prevalence Index = B/A = <u>3.455</u>
8.				Hydrophytic Vegetation Indicators:
9.				✓ Dominance Test is > 50%
10.	0			$\square Prevalence Index is \leq 3.0$
Total Cove	r:63.1			
Herb Stratum 50% of Total Cover:	0011	6 of Total Cover:	12.62	Morphological Adaptations ¹ (Provide supporting data in Remarks or on a separate sheet)
1. Cornus canadensis	40	\checkmark	FACU	Problematic Hydrophytic Vegetation ¹ (Explain)
2. Geranium erianthum	10		FACU	¹ Indicators of hydric soil and wetland hydrology must
3. Festuca rubra	10		FAC	be present, unless disturbed or problematic.
4. Calamagrostis canadensis			FAC	
5. Chamerion angustifolium			FACU	Plot size (radius, or length x width) <u>10m</u>
6. Sanguisorba canadensis			FACW	% Cover of Wetland Bryophytes (Where applicable)
7. Carex podocarpa			FAC	% Bare Ground _5
8. Aconitum delphinifolium	1		FAC	Total Cover of Bryophytes 10
9 Artemisia norvegica	0.1		FACU	
10.	0			Hydrophytic
Total Cove	r: 69.1			Vegetation
50% of Total Cover:		of Total Cover:	13.82	Present? Yes No
Remarks:				

Depth —	I	Matrix		ument the indicator or co Re	dox Feat		,		
(In all a a)	Color (mo	ist)	%	Color (moist)	%	Type ¹	Loc 2	Texture	Remarks
0-2			100					Fibric Organics	
2-5	10YR	3/2	95					Silt Loam	5% roots few semiangular gravel
5-8	10YR	3/3	95		_			Silt Loam	5% semiang grvl, cobbles, roots
8-10	10YR	3/2	95					Silt Loam	few semiang cobbles and gravel
10-13	10YR	4/3	95					Silt Loam	few semiang gravel and cobbles
13-23	10YR	3/3	90					Silt Loam	semiangular gravel and cobbles
				· ·			-	· .	
	tration D-	-Doplotion		uced Matrix ² Location				nnol M-Matrix	
Type: C=Concent		Depletion	I. R™=Reul			-			
Hydric Soil Indica				Indicators for P		4	oils:	7	
Histosol or Hist	tel (A1)			Alaska Color C		·	L	Alaska Gleyed Without Underlying Layer	Hue 5Y or Redder
Histic Epipedon				Alaska Alpine s	•	,		, , ,	
Hydrogen Sulfic	. ,			Alaska Redox	With 2.5Y	Hue		Other (Explain in Rem	di KS)
Thick Dark Sur	. ,)		³ One indicator of	hydrophy	tic vegetatio	on, one prir	nary indicator of wetland	i hvdroloav.
Alaska Gleyed (and an appropria					,
Alaska Redox (A	. ,	_,		⁴ Give details of c	olor chanc	e in Remark	(S		
Alaska Gleyed F	Pores (A1)							
Restrictive Layer (if	present):								
Type:								Hydric Soil Prese	nt? Yes 🔾 No 🖲
Type: Depth (inches): Remarks:								Hydric Soil Prese	nt? Yes ∪ No ♥
Depth (inches):								Hydric Soil Prese	nt? Yes ∪ No ♥
Depth (inches): Remarks: no hydric soil indicat	itors							Hydric Soil Prese	nt? Yes ∪ No ♥
Depth (inches): Remarks: no hydric soil indicat	itors	tors:							
Depth (inches): Remarks: no hydric soil indicat	itors , gy Indica		it)					Secondary Ir	dicators (two or more are required)
Depth (inches): Remarks: no hydric soil indicat HYDROLOGY Wetland Hydrolog Primary Indicators	itors gy Indica (any one i			Inundation V	fisible on A	verial Image	ry (B7)	Secondary Ir	idicators (two or more are required)
Depth (inches): Remarks: no hydric soil indicat HYDROLOGY Wetland Hydrolog Primary Indicators	itors gy Indica (any one i · (A1)		it)	Inundation V Sparsely Vec		-		Secondary Ir	dicators (two or more are required)
Depth (inches): Remarks: no hydric soil indicat HYDROLOGY Wetland Hydrolog Primary Indicators	tors gy Indica (any one i (A1) able (A2)			Sparsely Veg	etated Co	-		Secondary Ir Water S Drainag Oxidized	idicators (two or more are required) tained Leaves (B9) e Patterns (B10)
Depth (inches): Remarks: no hydric soil indicat HYDROLOGY Wetland Hydrolog Primary Indicators Surface Water High Water Ta	tors gy Indica (any one i (A1) able (A2) 3)			Sparsely Veg	etated Co s (B15)	ncave Surfa		Secondary Ir Water S Drainag Oxidized	idicators (two or more are required) tained Leaves (B9) e Patterns (B10) I Rhizospheres along Living Roots (C3) e of Reduced Iron (C4)
Depth (inches): Remarks: no hydric soil indicat HYDROLOGY Wetland Hydrolog Primary Indicators Surface Water High Water Ta Saturation (A3	tors gy Indica (any one i (A1) able (A2) 3) B1)			Sparsely Veg	etated Co s (B15) Ilfide Odor	ncave Surfac		Secondary Ir Water S Drainage Oxidized Presence Salt Dep	idicators (two or more are required) tained Leaves (B9) e Patterns (B10) I Rhizospheres along Living Roots (C3) e of Reduced Iron (C4)
Depth (inches): Remarks: no hydric soil indicat HYDROLOGY Wetland Hydrolog Primary Indicators Surface Water High Water Ta Saturation (A3 Water Marks (I	tors gy Indica (any one i (A1) able (A2) 3) (B1) osits (B2)			Sparsely Veg	etated Co s (B15) Ilfide Odor Water Tab	ncave Surfac (C1) le (C2)		Secondary Ir Water S Drainage Oxidized Presence Salt Dep Stunted	dicators (two or more are required) tained Leaves (B9) e Patterns (B10) Rhizospheres along Living Roots (C3) e of Reduced Iron (C4) iosits (C5)
Depth (inches): Remarks: no hydric soil indicat HYDROLOGY Wetland Hydrolog Primary Indicators Surface Water High Water Ta Saturation (A3 Water Marks (I Sediment Depo	tors gy Indica (any one i (A1) able (A2) 3) B1) osits (B2) (B3)			Sparsely Veg Marl Deposit Hydrogen Su Dry-Season	etated Co s (B15) Ilfide Odor Water Tab	ncave Surfac (C1) le (C2)		Secondary Ir Secondary Ir Water S Drainag Oxidized Presence Salt Dep Stunted Geomor	dicators (two or more are required) tained Leaves (B9) e Patterns (B10) Rhizospheres along Living Roots (C3) e of Reduced Iron (C4) iosits (C5) or Stressed Plants (D1)
Depth (inches): Remarks: no hydric soil indicat HYDROLOGY Wetland Hydrolog Primary Indicators Surface Water High Water Ta Saturation (A3 Water Marks (I Sediment Depo Drift Deposits (tors gy Indica (any one i (A1) able (A2) 3) B1) osits (B2) (B3) irust (B4)			Sparsely Veg Marl Deposit Hydrogen Su Dry-Season	etated Co s (B15) Ilfide Odor Water Tab	ncave Surfac (C1) le (C2)		Secondary Ir Water S Drainage Oxidized Presence Salt Dep Stunted Geomor Shallow	dicators (two or more are required) tained Leaves (B9) e Patterns (B10) Rhizospheres along Living Roots (C3) e of Reduced Iron (C4) osits (C5) or Stressed Plants (D1) phic Position (D2)
Depth (inches): Remarks: no hydric soil indicat HYDROLOGY Wetland Hydrolog Primary Indicators Surface Water High Water Ta Saturation (A3 Water Marks (I Sediment Depo Drift Deposits (Algal Mat or Cr	tors gy Indica (any one i (A1) able (A2) (B1) osits (B2) (B3) irust (B4) (B5)			Sparsely Veg Marl Deposit Hydrogen Su Dry-Season	etated Co s (B15) Ilfide Odor Water Tab	ncave Surfac (C1) le (C2)		Secondary Ir Water S Drainage Oxidized Presence Salt Dep Stunted Geomor Shallow Microtop	dicators (two or more are required) tained Leaves (B9) e Patterns (B10) Rhizospheres along Living Roots (C3) e of Reduced Iron (C4) iosits (C5) or Stressed Plants (D1) obic Position (D2) Aquitard (D3)
Depth (inches): Remarks: no hydric soil indicat HYDROLOGY Wetland Hydrolog Primary Indicators Surface Water High Water Ta Saturation (A3 Water Marks (I Sediment Depo Drift Deposits (Algal Mat or Cr Iron Deposits (tors gy Indica (any one i (A1) able (A2) B1) osits (B2) (B3) irust (B4) (B5) racks (B6)	is sufficien		Sparsely Veg	etated Co s (B15) Ilfide Odor Water Tab	ncave Surfac (C1) le (C2)		Secondary Ir Water S Drainage Oxidized Presence Salt Dep Stunted Geomor Shallow Microtop	dicators (two or more are required) tained Leaves (B9) e Patterns (B10) l Rhizospheres along Living Roots (C3) e of Reduced Iron (C4) osits (C5) or Stressed Plants (D1) obic Position (D2) Aquitard (D3) oographic Relief (D4)
Depth (inches): Remarks: no hydric soil indicat HYDROLOGY Wetland Hydrolog Primary Indicators Surface Water High Water Ta Saturation (A3 Water Marks (I Sediment Depo Drift Deposits (Algal Mat or Cr Iron Deposits (Surface Soil Cr	tors gy Indica (any one i (A1) able (A2) B1) osits (B2) (B3) rust (B4) (B5) racks (B6) ns:	is sufficien	at)	Sparsely Veg	etated Co s (B15) Ilfide Odor Water Tab in in Rema	ncave Surfac (C1) le (C2)		Secondary Ir Water S Drainage Oxidized Presence Salt Dep Stunted Geomor Shallow Microtop	dicators (two or more are required) tained Leaves (B9) e Patterns (B10) l Rhizospheres along Living Roots (C3) e of Reduced Iron (C4) osits (C5) or Stressed Plants (D1) obic Position (D2) Aquitard (D3) oographic Relief (D4)
Depth (inches): Remarks: no hydric soil indicat HYDROLOGY Wetland Hydrolog Primary Indicators Surface Water High Water Ta Saturation (A3 Water Marks (I Sediment Depo Drift Deposits (Algal Mat or Cr Iron Deposits (Surface Soil Cr Field Observation	tors gy Indica (any one i (A1) able (A2) 3) B1) osits (B2) (B3) irust (B4) (B5) irust (B4) (B5) iracks (B6) ns: sent?	s sufficien		Sparsely Veg Marl Deposit Hydrogen Su Dry-Season Other (Expla	etated Co s (B15) Ilfide Odor Nater Tab in in Rema as):	ncave Surfac (C1) le (C2)	ce (B8)	Secondary Ir Water S Drainage Oxidized Presence Salt Dep Stunted Geomor Shallow Microtop	dicators (two or more are required) tained Leaves (B9) e Patterns (B10) Rhizospheres along Living Roots (C3) e of Reduced Iron (C4) osits (C5) or Stressed Plants (D1) obic Position (D2) Aquitard (D3) oographic Relief (D4) tral Test (D5)
Depth (inches): Remarks: no hydric soil indicat HYDROLOGY Wetland Hydrolog Primary Indicators Surface Water High Water Ta Saturation (A3 Water Marks (I Sediment Depo Drift Deposits (Algal Mat or Cr Iron Deposits (Surface Soil Cr Field Observation Surface Water Prese Water Table Present Saturation Present	tors gy Indica (any one i (A1) able (A2) B1) osits (B2) (B3) irust (B4) (B5) racks (B6) ns: sent? ent? t?	s sufficien Yes (Yes () No 🖲	Sparsely Veg Marl Deposit Hydrogen Su Dry-Season Other (Expla	etated Co s (B15) Ilfide Odor Water Tab in in Rema es):	ncave Surfac (C1) le (C2)	ce (B8)		dicators (two or more are required) tained Leaves (B9) e Patterns (B10) Rhizospheres along Living Roots (C3) e of Reduced Iron (C4) iosits (C5) or Stressed Plants (D1) phic Position (D2) Aquitard (D3) iographic Relief (D4) tral Test (D5)
Depth (inches): Remarks: no hydric soil indicat HYDROLOGY Wetland Hydrolog Primary Indicators Surface Water High Water Ta Saturation (A3 Water Marks (I Sediment Depo Drift Deposits (Algal Mat or Cr Iron Deposits (Surface Soil Cr Field Observation Surface Water Present Water Table Present Saturation Present (includes capillary 1)	tors gy Indica (any one i (A1) able (A2) B1) osits (B2) (B3) irust (B4) (B5) racks (B6) ns: sent? ent? ent? fringe)	Yes (Yes (Yes () No ()) No ()) No ()	Sparsely Veg Marl Deposit Hydrogen Su Dry-Season Other (Expla Depth (inche	etated Co s (B15) Ilfide Odor Water Tab in in Rema as): as): as):	ncave Surfac (C1) le (C2) arks)	wetla		dicators (two or more are required) tained Leaves (B9) e Patterns (B10) Rhizospheres along Living Roots (C3) e of Reduced Iron (C4) iosits (C5) or Stressed Plants (D1) phic Position (D2) Aquitard (D3) iographic Relief (D4) tral Test (D5)

no wetland hydrology indicators