

WETLAND DETERMINATION DATA FORM - Alaska Region

Project/Site: Susitna-Watana Hydroelectric Project Borough/City: Matanuska-Susitna Borough Sampling Date: 05-Aug-13
 Applicant/Owner: Alaska Energy Authority Sampling Point: **SW13_T100_08**
 Investigator(s): BAB Landform (hillside, terrace, hummocks etc.): Lowland
 Local relief (concave, convex, none): hummocky Slope: 3.5 % / 2.0 ° Elevation: 791
 Subregion: Copper River Basin Lat.: 62.6158786844 Long.: -147.42373039 Datum: WGS84
 Soil Map Unit Name: _____ NWI classification: **PSS1/4B**

Are climatic/hydrologic conditions on the site typical for this time of year? Yes No (If no, explain in Remarks.)
 Are Vegetation , Soil , or Hydrology significantly disturbed? Are "Normal Circumstances" present? Yes No
 Are Vegetation , Soil , or Hydrology naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS - Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present? Yes <input checked="" type="radio"/> No <input type="radio"/> Hydric Soil Present? Yes <input checked="" type="radio"/> No <input type="radio"/> Wetland Hydrology Present? Yes <input checked="" type="radio"/> No <input type="radio"/>	Is the Sampled Area within a Wetland? Yes <input checked="" type="radio"/> No <input type="radio"/>
Remarks: near the top of a long gentle slope	

VEGETATION -Use scientific names of plants. List all species in the plot.

Tree Stratum	Absolute % Cover	Dominant Species?	Indicator Status	Dominance Test worksheet:
1. _____	0	<input type="checkbox"/>	_____	Number of Dominant Species That are OBL, FACW, or FAC: <u>6</u> (A)
2. _____	0	<input type="checkbox"/>	_____	Total Number of Dominant Species Across All Strata: <u>6</u> (B)
3. _____	0	<input type="checkbox"/>	_____	Percent of dominant Species That Are OBL, FACW, or FAC: <u>100.0%</u> (A/B)
4. _____	0	<input type="checkbox"/>	_____	Prevalence Index worksheet: Total % Cover of: _____ Multiply by: OBL Species <u>0</u> x 1 = <u>0</u> FACW Species <u>57.1</u> x 2 = <u>114.2</u> FAC Species <u>35.1</u> x 3 = <u>105.3</u> FACU Species <u>0</u> x 4 = <u>0</u> UPL Species <u>0</u> x 5 = <u>0</u> Column Totals: <u>92.2</u> (A) <u>219.5</u> (B) Prevalence Index = B/A = <u>2.381</u>
5. _____	0	<input type="checkbox"/>	_____	
Total Cover:			<u>0</u>	
Sapling/Shrub Stratum	50% of Total Cover: <u>0</u>	20% of Total Cover: <u>0</u>		
1. <u>Picea mariana</u>	20	<input checked="" type="checkbox"/>	FACW	
2. <u>Betula nana</u>	15	<input checked="" type="checkbox"/>	FAC	
3. <u>Ledum groenlandicum</u>	0.1	<input type="checkbox"/>	FAC	
4. <u>Ledum decumbens</u>	20	<input checked="" type="checkbox"/>	FACW	
5. <u>Vaccinium vitis-idaea</u>	2	<input type="checkbox"/>	FAC	
6. <u>Vaccinium uliginosum</u>	8	<input type="checkbox"/>	FAC	
7. <u>Empetrum nigrum</u>	2	<input type="checkbox"/>	FAC	
8. _____	0	<input type="checkbox"/>	_____	
9. _____	0	<input type="checkbox"/>	_____	
10. _____	0	<input type="checkbox"/>	_____	
Total Cover:			<u>67.1</u>	
Herb Stratum	50% of Total Cover: <u>33.55</u>	20% of Total Cover: <u>13.42</u>		
1. <u>Eriophorum vaginatum</u>	6	<input checked="" type="checkbox"/>	FACW	
2. <u>Carex bigelowii</u>	6	<input checked="" type="checkbox"/>	FAC	
3. <u>Equisetum sylvaticum</u>	2	<input type="checkbox"/>	FAC	
4. <u>Petasites frigidus</u>	1	<input type="checkbox"/>	FACW	
5. <u>Pedicularis labradorica</u>	0.1	<input type="checkbox"/>	FACW	
6. <u>Rubus chamaemorus</u>	10	<input checked="" type="checkbox"/>	FACW	
7. _____	0	<input type="checkbox"/>	_____	
8. _____	0	<input type="checkbox"/>	_____	
9. _____	0	<input type="checkbox"/>	_____	
10. _____	0	<input type="checkbox"/>	_____	
Total Cover:			<u>25.1</u>	
50% of Total Cover:	<u>12.55</u>	20% of Total Cover:	<u>5.02</u>	

Hydrophytic Vegetation Indicators:

Dominance Test is > 50%

Prevalence Index is ≤ 3.0

Morphological Adaptations¹ (Provide supporting data in Remarks or on a separate sheet)

Problematic Hydrophytic Vegetation¹ (Explain)

¹ Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Plot size (radius, or length x width) 10m

% Cover of Wetland Bryophytes (Where applicable) _____

% Bare Ground 2

Total Cover of Bryophytes 55

Hydrophytic Vegetation Present? Yes No

Remarks: small patches of sedge moss bogs scattered throughout

SOIL

Sampling Point: **SW13_T100_08**

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators)

Depth (inches)	Matrix		Redox Features				Texture	Remarks
	Color (moist)	%	Color (moist)	%	Type ¹	Loc ²		
0-4		100					Fibric Organics	
4-13		100					Hemic Organics	

¹Type: C=Concentration. D=Depletion. RM=Reduced Matrix ² Location: PL=Pore Lining. RC=Root Channel. M=Matrix

<p>Hydric Soil Indicators:</p> <input type="checkbox"/> Histosol or Histel (A1) <input checked="" type="checkbox"/> Histic Epipedon (A2) <input type="checkbox"/> Hydrogen Sulfide (A4) <input type="checkbox"/> Thick Dark Surface (A12) <input type="checkbox"/> Alaska Gleyed (A13) <input type="checkbox"/> Alaska Redox (A14) <input type="checkbox"/> Alaska Gleyed Pores (A15)	<p>Indicators for Problematic Hydric Soils:³</p> <input type="checkbox"/> Alaska Color Change (TA4) ⁴ <input type="checkbox"/> Alaska Alpine swales (TA5) <input type="checkbox"/> Alaska Redox With 2.5Y Hue <input type="checkbox"/> Alaska Gleyed Without Hue 5Y or Redder Underlying Layer <input type="checkbox"/> Other (Explain in Remarks)
--	---

³ One indicator of hydrophytic vegetation, one primary indicator of wetland hydrology, and an appropriate landscape position must be present
⁴ Give details of color change in Remarks

Restrictive Layer (if present): Type: ice rich frozen soils Depth (inches): 13	Hydric Soil Present? Yes <input checked="" type="radio"/> No <input type="radio"/>
--	---

Remarks:

HYDROLOGY

<p>Wetland Hydrology Indicators:</p> <p><u>Primary Indicators (any one is sufficient)</u></p> <input type="checkbox"/> Surface Water (A1) <input type="checkbox"/> Inundation Visible on Aerial Imagery (B7) <input type="checkbox"/> High Water Table (A2) <input type="checkbox"/> Sparsely Vegetated Concave Surface (B8) <input checked="" type="checkbox"/> Saturation (A3) <input type="checkbox"/> Marl Deposits (B15) <input type="checkbox"/> Water Marks (B1) <input type="checkbox"/> Hydrogen Sulfide Odor (C1) <input type="checkbox"/> Sediment Deposits (B2) <input type="checkbox"/> Dry-Season Water Table (C2) <input type="checkbox"/> Drift Deposits (B3) <input type="checkbox"/> Other (Explain in Remarks) <input type="checkbox"/> Algal Mat or Crust (B4) <input type="checkbox"/> Iron Deposits (B5) <input type="checkbox"/> Surface Soil Cracks (B6)	<p><u>Secondary Indicators (two or more are required)</u></p> <input type="checkbox"/> Water Stained Leaves (B9) <input type="checkbox"/> Drainage Patterns (B10) <input type="checkbox"/> Oxidized Rhizospheres along Living Roots (C3) <input type="checkbox"/> Presence of Reduced Iron (C4) <input type="checkbox"/> Salt Deposits (C5) <input type="checkbox"/> Stunted or Stressed Plants (D1) <input type="checkbox"/> Geomorphic Position (D2) <input checked="" type="checkbox"/> Shallow Aquitard (D3) <input type="checkbox"/> Microtopographic Relief (D4) <input checked="" type="checkbox"/> FAC-neutral Test (D5)
---	---

<p>Field Observations:</p> Surface Water Present? Yes <input type="radio"/> No <input checked="" type="radio"/> Depth (inches): Water Table Present? Yes <input type="radio"/> No <input checked="" type="radio"/> Depth (inches): Saturation Present? Yes <input checked="" type="radio"/> No <input type="radio"/> Depth (inches): 6 (includes capillary fringe)	Wetland Hydrology Present? Yes <input checked="" type="radio"/> No <input type="radio"/>
---	---

Describe Recorded Data (stream gauge, monitor well, aerial photos, previous inspection) if available:

Remarks:
 Community contains areas that are more wet than this, which probably do have a water table.