

GOOSE CK PHOTOS

- 9801 view d/s Sustna (TLB) to Goose Ck. from confluence
- 9802 view w/s Sustna (TLB) from confluence
- 9803 view up Goose Ck. fan
- 9804 "
- 9805 view across Goose to Gooding TLB
- 9806 view d/s Goose to Sus. Area
- 9807 view of Goose cont. w/ Su
- 9809 view up Goose ck fan. People standing on top of fan deposits
- 9810 view w/s Sustna TLB from conf.
- 9811 view w/s Goose from conf.
- 9812 view w/s Goose Ck.
- 9813 "
- 9814 view across Goose to eroding TLB
- 9815 surface material on fan (Goose)
- 9816 embriicate large material on fan
- 9817 view down Goose Ck.
- 9818 Arc material deposit on fan

UNT 228.5 PHOTOS

- 1047 view w/s UNT 228.5 from conf.
- 1048 view d/s Sustna TLB from conf.
- 1049 sediment deposition on fan
- 1050 view w/s UNT 228.5
- 1051 sediment deposition in abandoned right channel view w/s
- 1052 " " "
- 1053 " " deposited boulder material
- 1054 " " "
- 1055 " " "
- 1056 view d/s abandoned f. channel
- 1057 view w/s UNT 228.5 from split channel location
- 1058 " " "
- 1059 " " "
- 1060 view w/s UNT 228.5 smyle channel
- 1061 " " "
- 1062 view d/s UNT 228.5

Notes in the Rain