


OSHETNA



Mouth of Oshetna Confined by Fan/TCE
 Ice Scars ~ 10' above WSE
 Plane bed river - Incised down into its fan
 Heavily armored
 Vertically stable
 Significant sediment point source

PHOTOS

COMMENT

#	COMMENT
9710	Ice paving TLB - just ups of Osh. conf.
9716	"
9724	Surface material @ S1
9725	View d/s through S1 transect material on Oshetna fan
9726	View up Oshetna, eroding TCE on TRB
9727	View ups from mouth
9728	view TRB surface from TLB
9729	view TRB from TLB
9730	view down TLB Susitha from Osh conf.
9731	view up Susitha TLB from d/s of Osh conf.
9732	view fan from d/s conf.
9733	large embriicate material on fan transported (loose) material on fan
9734	wake of transported material behind bowlders on fan
9735	
9736	
9737	View d/s S2 through transect
9738	Surface material on S2
9739	wet slip on TLB Oshetna (loose fine material)
9740	View up Osh.
9742	large, coarse G/B above eroding TCE
9743	view d/s on Oshetna TLB

Return to the Rain

OSHEETA CONFERENCE

BAR SURVEY @ MOUTH

Boulder	Count	(ICE ??)
510	410	380
506	600	400
410	470	480
370	500	400
430	900	350
460	440	400
550	430	580
400	480	560
450	380	470
350	470	500
500	720	460
410	500	440
570	430	490
430	490	390
380	330	320
380	320	380
400	300	420
400	380	360

BC	BWS	#
180		
252		
360		
512		
720		
1024		
Size		
256		9
340		73
512		18
720		1
		101

8/12/14
