


Date and Time: 7/18/14 Northing / Lat: 3205188.5'  
 River: SUSITNA Easting / Long: 1830847.3'  
 X-Sec/PRM: PRM 173.6 R Bank Height (ft): 13'  
 Field Book #: MDH Failure Mode: —  
 Sampled By: MDH, RV Root Depth (ft): —  
 Comments: TCE SURFACE Bank Angle (deg): —  
 comprised of rounded granites  
 and very thick >1 ft angular  
 layer on top of bank  
 Large Birch and Spruce w/ some alders

Bank Samples: S1A, S1B TOTAL 2 SAMPLES AT SITE  
 P 8268 - view of bank  
 P 8269 - Pic of sample.



QC1 RAV

Photo Backup: 648