



River / Tributary: SUSITNA R.
 Site: PRM 173.8
 Date / Time: 7/18/14
 Field Book #: MDH
 Sample Number: S3
 Subsurface Sample Performed with Surface? N
 Sample Type: Main Ch Trib Fan Toe of Bank Lateral Feature

Crew: MDH, PV
 Length & Interval: _____
 Northing / Lat: 3205163.5
 Easting / Long: 1832102.3
 Comments: BOULDER COUNT
8290 - View v/s across boulder S
8263 - Site before sampling - view v/s
8262 - View d/s site before sampling

| Size (mm) | Left | Sum | Cum | Size (mm) | Center | Sum | Cum | Size (mm) | Right | Sum | Cum |
|-----------|------|-----|-----|-----------|--------|-----|-----|-----------|-------|-----|-----|
| <2 | | | | <2 | | | | <2 | | | |
| 2 | | | | 2 | | | | 2 | | | |
| 2.8 | | | | 2.8 | | | | 2.8 | | | |
| 4 | | | | 4 | | | | 4 | | | |
| 5.6 | | | | 5.6 | | | | 5.6 | | | |
| 8 | | | | 8 | | | | 8 | | | |
| 11 | | | | 11 | | | | 11 | | | |
| 16 | | | | 16 | | | | 16 | | | |
| 22.5 | | | | 22.5 | | | | 22.5 | | | |
| 32 | | | | 32 | | | | 32 | | | |
| 45 | | | | 45 | | | | 45 | | | |
| 64.0 | | | | 64.0 | | | | 64.0 | | | |
| 90 | | | | 90 | | | | 90 | | | |
| 128 | | | | 128 | | | | 128 | | | |
| 180 | | | | 180 | /// | 3 | 58 | 180 | | | |
| 256 | | | | 256 | | 38 | 96 | 256 | | | |
| 360 | | | | 360 | | 38 | 134 | 360 | | | |
| 512 | | | | 512 | | 1 | 135 | 512 | | | |
| 720 | | | | 720 | | | | 720 | | | |

LEFT COUNT

| | | | | |
|--|--|--|--|--|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

CENTER COUNT

| | | | | |
|--|--|--|--|--|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

RIGHT COUNT

| | | | | |
|--|--|--|--|--|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

QC1 RAV

Photo Backup 8391

Page 1 of 1