

Date and Time: 7/21/14 1030	Northing / Lat: 3226514.0
River: SUSITNA	Easting / Long: 1872458.3
X-Sec / PRM: 184.77	Bank Height (ft): 4.8'
Field Book #: MDH	Failure Mode: ice sheared
Sampled By: MDH, RAV	Root Depth (ft): 2.5'
Comments:	Bank Angle (deg): vertical (upper) = 2.5' sloped (lower) = 2.3' vertical @ 15°
Sample Number: S1A-S1-B	Bank Samples 2 TOTAL

PHOTOS: 8414 - bank - site on arrival, TRB ~ 40' d/s from XSEC PIN (184.7)  
8415 - soil profile

