

LR-2

Date and Time: 8/26/14

Northing / Lat: 2968805.9

River: SUSITNA

Easting / Long: 1618148.2

X-Sec /PRM: PRM B3, D

Bank Height (ft): 7.8' above WSE, 4.6' above gravel core

Field Book #: -

Failure Mode: cantilever

Sampled By: MDH, BT, RV

Root Depth (ft): 4'

Comments:

Bank Angle (deg): vertical

Sample Number: S4

Bank Samples 2 SAMPLES

Old Floodplain surface - Large old poplars, spruce, Early cantilevered bank - LWD source

Cored spruce \varnothing 1.4' w 180 yrs

S4A

S4B

