

LR-3

Date and Time: 8/27/14 1430 Northing / Lat: 2838140.4
 River: SUSITNA Easting / Long: 1596781.2
 X-Sec / PRM: PRM 51.2 Bank Height (ft): 5' above gravels and WSE
 Field Book #: — Failure Mode: cantilever
 Sampled By: MDH, BT, RV Root Depth (ft): ~3'
 Comments: Bank Angle (deg): vertical
 P130 - Bank Bank Samples: 3 SAMPLES → SA, SB, SC

MFP surface → poplars Ø ~1', tall spruce, thick underbrush
 Gravel core should be @ 5' below top of bank. Any missing strat to make 5' should be organics @ top of subma

