



Date and Time: B/27/14 1315 Northing / Lat: 1604786.6 E / 2852456.8 N

River: SUSITNA Easting / Long: 3.7' above gravel core / 4.2' above WSE

X-Sec / PRM: PRM 55.6 Bank Height (ft): L

Field Book #: - Failure Mode: amblymer

Sampled By: MDH, BT, RV Root Depth (ft): 3.4'

Comments: 127-129 Bank Angle (deg): Vertical

Sample Number: 54

Bank Samples 3 SAMPLES A, B, C

Photos:

(ft)	Lithology	Lithologic Description	Special Features
0	(X)	clean f. sand - 1' 1'	
0.3	SS	no roots - recent dep.	
0.3	SS	f. silty sand - Fe stain - 0.3'	
0.5	SS	organics - 0.5'	
0.4	(X)	f. sand some roots - 0.4'	
0.4	SS	f. silty sand - Fe stain - 0.4'	
0.1	SS	organics - 0.1'	
1	(X)	v. fine silty sand - Fe-stain - 1'	
1	SS	some roots	
1	SS	clean fine to med sand some roots	
1	SS	GRAVEL CORE	