


Date and Time: 8/20/14 1700 Northing / Lat: 2773919.7  
 River: SUSITNA Easting / Long: 1573590.1  
 X-Sec / PRM: PRM 35.8 Bank Height (ft): 7.1' to gravels ~ 7.4' to WSE  
 Field Book #: — Failure Mode: cantilever  
 Sampled By: MDH, BT, RV Root Depth (ft): 2.6'  
 Comments: Bank Angle (deg): vertical  
 PHOTOS: 332-334 Bank Samples: S10 A, B, C

OLD FLOODPLAIN SURFACE

LR-4



S10-A

S10-B

S10-C