

42-4

Date and Time: 8/28/14 1530 Northing / Lat: 27 814 95.9
 River: SUSITNA Easting / Long: 15 774 58.7
 X-Sec / PRM: 37.3 Bank Height (ft): 6.4' to WSE → No contact w/ gravel
 Field Book #: — Failure Mode: cantilever
 Sampled By: MWH, BT, PV Root Depth (ft): ~ 2.5'
 Comments: Bank Angle (deg): vertical
 Photos: 345-351 Bank Samples: S11 A, B, C

MATURE FLOODPLAIN SURFACE

BAND OF DEAD ALDERS + POPLARS FROM TOP OF BANK TO ~ 75' INLAND FROM TOP OF BANK → SPRUCE ESTABLISHMENT IN SW BAND

