

Date and Time: 8/28/14 1000 Northing / Lat: 2832409.2  
 River: SUSITNA Easting / Long: 1608147.4  
 X-Sec /PRM: PRM 52.0 Bank Height (ft): 3.6' to base gravels; 5.1' to WSE  
 Field Book #: - Failure Mode: cantilever  
 Sampled By: MDH, BT, RV Root Depth (ft): 2'  
 Comments: Bank Angle (deg): vertical

LR-3

PHOTOS: 207-208 Bank Samples: 3 TOTAL -> S1A, S1B, S1C

Mature to old Floodplain Surface  
Recent sand dep. on top of surface. (2 fairly recent sed. events)  
Dying trees along floodplain margins

