

# Surface Sample Data Sheet



River / Tributary: SUSITNA  
 Site: IRM 196.5  
 Date / Time: 8/16/14 1400  
 Field Book #:       
 Sample Number: S2  
 Subsurface Sample Performed with Surface?     
 Sample Type: Main Ch Trib Fan Toe of Bank Lateral Feature

Crew: MDH, CUB, RAV  
 Length & Interval: 100' x 1'  
 Northing / Lat: 3230355.4  
 Easting / Long: 1929604.1  
 Comments: HEAD OF LARGE CREEK @ HEAD OF HIGH ELEVATION  
KLEIN) - FROM SANDS PROBABLY DERIVED FROM  
WATANA CREEK

| Size (mm) | Left | Sum | Cum | Size (mm) | Center | Sum | Cum | Size (mm) | Right | Sum | Cum |
|-----------|------|-----|-----|-----------|--------|-----|-----|-----------|-------|-----|-----|
| <2        |      |     |     | <2        |        |     |     | <2        |       |     |     |
| 2         |      |     |     | 2         |        |     |     | 2         |       |     |     |
| 2.8       |      |     |     | 2.8       |        |     |     | 2.8       |       |     |     |
| 4         |      |     |     | 4         |        |     |     | 4         |       |     |     |
| 5.6       |      | 1   | 1   | 5.6       |        |     |     | 5.6       |       |     |     |
| 8         |      | 1   | 2   | 8         |        |     |     | 8         |       |     |     |
| 11        |      | 9   | 11  | 11        |        |     |     | 11        |       |     |     |
| 16        |      | 26  | 37  | 16        |        |     |     | 16        |       |     |     |
| 22.5      |      | 31  | 68  | 22.5      |        |     |     | 22.5      |       |     |     |
| 32        |      | 21  | 89  | 32        |        |     |     | 32        |       |     |     |
| 45        |      | 6   | 95  | 45        |        |     |     | 45        |       |     |     |
| 64.0      |      | 2   | 97  | 64.0      |        |     |     | 64.0      |       |     |     |
| 90        |      | 1   | 98  | 90        |        |     |     | 90        |       |     |     |
| 128       |      | 2   | 100 | 128       |        |     |     | 128       |       |     |     |
| 180       |      |     |     | 180       |        |     |     | 180       |       |     |     |
| 256       |      |     |     | 256       |        |     |     | 256       |       |     |     |
| 360       |      |     |     | 360       |        |     |     | 360       |       |     |     |
| 512       |      |     |     | 512       |        |     |     | 512       |       |     |     |
| 720       |      |     |     | 720       |        |     |     | 720       |       |     |     |

LEFT COUNT

|  |  |  |  |  |
|--|--|--|--|--|
|  |  |  |  |  |
|  |  |  |  |  |
|  |  |  |  |  |
|  |  |  |  |  |

CENTER COUNT

|  |  |  |  |  |
|--|--|--|--|--|
|  |  |  |  |  |
|  |  |  |  |  |
|  |  |  |  |  |
|  |  |  |  |  |

RIGHT COUNT

|  |  |  |  |  |
|--|--|--|--|--|
|  |  |  |  |  |
|  |  |  |  |  |
|  |  |  |  |  |
|  |  |  |  |  |

QC1 RAV

Photo Backup 564

Page 1 of 2



River / Tributary: SUSITNA  
 Site: 19870  
 Date: 8/16/14

Additional Comments

---

---

---

---

---

---

---

---

---

---

---

Photo Log

| Photo # | Description  |
|---------|--|
| 413     | surface  |
| 414     | view w/s   |
| 415     | larger material likely derived from local eroding source |
| 416     | view w/s   |
|         |  |
|         |  |
|         |  |
|         |  |
|         |  |
|         |  |
|         |  |
|         |  |
|         |  |
|         |  |
|         |  |
|         |  |
|         |  |
|         |  |
|         |  |
|         |  |
|         |  |
|         |  |