

Surface Sample Data Sheet



River / Tributary: 4th of July CR
 Site: n/a
 Date / Time: 6/22/14 12:15 pm
 Field Book #: DBT
 Sample Number: S2
 Subsurface Sample Performed with Surface? NO
 Sample Type: Main Ch Trib Fan Toe of Bank Lateral Feature

Crew: DBT, RV
 Length & Interval: 100', 1'
 Comments: along bank attached bar - left side b/t XS3 & 5 (LEFT)
 Northing / Lat: 3185422.5 @
 Easting / Long: 1672813.8
 Comments: along right bank b/t XS3-1 (RIGHT)

Size (mm)	Left	Sum	Cum %	Size (mm)	Center	Sum	Cum %	Size (mm)	Right	Sum	Cum %	Cum Ave
< 2				< 2				< 2				
2				2				2				
2.8				2.8				2.8				
4		1	1	4				4				
5.6		1	2	5.6				5.6		1	1	
8		1	3	8				8		3	4	
11		7	10	11				11		2	6	
16		9	19	16				16		2	8	
22.5		8	27	22.5				22.5		4	12	
32		14	41	32				32		7	19	
45		8	49	45				45		8	27	
64.0		17	66	64.0				64.0		14	43	41
90		12	78	90				90		22	65	63
128		14	92	128				128		14	79	77
180		4	96	180				180		12	91	89
256		3	99	256				256		7	98	96
360		1	100	360				360		1	99	97
720				720				720		3	102	100

PROVISIONAL

LEFT COUNT

CENTER COUNT

RIGHT COUNT

QC1 RAV

Photo Backup 258

Page 1 of 2

* covering main water back-up taken

Surface Sample Data Sheet



River / Tributary: 4th JULY
 Site: n/g
 Date: 6/22/14

Additional Comments

Photo Log

Photo #	Description
223	bank attached bar along TLB
224	location of transect along TRB

PROVISIONAL

QC1 RAV

Photo Backup 259

Page 2 of 2