

Surface Sample Data Sheet



River / Tributary: 5th July
 Site: _____
 Date / Time: 6-23-14 2:10pm
 Field Book #: DBS
 Sample Number: 33
 Subsurface Sample Performed with Surface? NO
 Sample Type: Main Ch Trib Fan Toe of Bank Lateral Feature

Crew: DT, RV
 Length & Interval: 100' 1'
 Comments: Surface from last flood event?
 Northing / Lat: 316 2 231.5
 Easting / Long: 164 7399.0
 Comments: Tran along bar on #TRB
l/t XS 2 & 55

Photo to:
 277 - looking
 d/s from J
 XS-5

Size (mm)	Left	Sum	Cum %	Size (mm)	Center	Sum	Cum %	Size (mm)	Right	Sum	Cum %	Cum Ave
<2				<2				<2				
2				2				2				
2.8				2.8				2.8				
4				4				4				
5.6		2	2	5.6				5.6				
8				8				8				
11		1	3	11				11				
16		6	9	16				16				
22.5		10	19	22.5				22.5				
32		18	37	32				32				
45		13	50	45				45				
64.0		13	63	64.0				64.0				
90		12	75	90				90				
128		11	86	128				128				
180		6	92	180				180				
256		4	96	256				256				
360		4	100	360				360				
720				720				720				

LEFT COUNT

CENTER COUNT

RIGHT COUNT

QC1 RAV

Photo Backup 291
300

Page 1 of 1

