

Provisional data subject to revision
Surface Sample Data Sheet



River / Tributary: Fog Cr.
 Site: _____
 Date / Time: 7/12/14 1138
 Field Book #: _____
 Sample Number: S4
 Subsurface Sample Performed with Surface? N
 Sample Type: Main Ch Trib Fan Toe of Bank Lateral Feature

Crew: RET, RAV
 Length & Interval: 100', 1'
 Northing / Lat: 3208617.1
 Easting / Long: 1855253.5
 Comments: Fine Appears to be mobile layer - loose gravels. No sand layer present on sampled surface

| Size (mm) | Left | Sum | Cum | Size (mm) | Center - S4 | Sum | Cum | Size (mm) | Right | Sum | Cum |
|-----------|------|-----|-----|-----------|-------------|-----|-----|-----------|-------|-----|-----|
| < 2 | | | | < 2 | | | | < 2 | | | |
| 2 | | | | 2 | | | | 2 | | | |
| 2.8 | | | | 2.8 | | | | 2.8 | | | |
| 4 | | | | 4 | | | | 4 | | | |
| 5.6 | | | | 5.6 | | | | 5.6 | | | |
| 8 | | | | 8 | | 4 | 4 | 8 | | | |
| 11 | | | | 11 | | 7 | 11 | 11 | | | |
| 16 | | | | 16 | | 15 | 26 | 16 | | | |
| 22.5 | | | | 22.5 | | 26 | 52 | 22.5 | | | |
| 32 | | | | 32 | | 20 | 72 | 32 | | | |
| 45 | | | | 45 | | 16 | 88 | 45 | | | |
| 64.0 | | | | 64.0 | | 7 | 95 | 64.0 | | | |
| 90 | | | | 90 | | 4 | 99 | 90 | | | |
| 128 | | | | 128 | | 1 | 100 | 128 | | | |
| 180 | | | | 180 | | | | 180 | | | |
| 256 | | | | 256 | | | | 256 | | | |
| 360 | | | | 360 | | | | 360 | | | |
| 512 | | | | | | | | | | | |
| 720 | | | | 720 | | | | 720 | | | |

LEFT COUNT

| | | | | |
|--|--|--|--|--|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

CENTER COUNT

| | | | | |
|--|--|--|--|--|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

RIGHT COUNT

| | | | | |
|--|--|--|--|--|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

QC1 RAV

Photo Backup 689

