

Date & Time: 3-20-2014 1700

Crew: BT, MP, RK

Sheet 1 of 1

Location: Chulitna - 2 ~ 500

Weather: clear

Camera: # SW6-Gopro - 3

GPS Unit: PDX

Comments: Camera 1 Photo 535 Left channel looking right, 536 looking US from centerline channel, 537 looking DS from centerline channel (Chob), 538 River right looking to left

(A) Sample #	(B) GPS Point #	(D) Snow Depth (ft)	(E) Ice Thickness (ft)	(F) Top of Ice to Bed Distance (ft)	(G) Flow Depth (F - E) (ft)	(H) Frazil Ice Present?	(I) Anchor Ice Present?	(J) Freeboard Height (ft)	(K) Camera Height above Bed (ft)	(L) Video #	(M) Comments / Bed Description
S1	1	0.3	2.6 ft	68	3.5	No	No	0.2	2	1591	video appears cloudy
S2	2	0.3	2.6 ft	78	4.3	No	No	0	2	768	
S3	3	0.3	2.4 ft	75	4.25	No	No	0.1	2	3	
S4	4	0.3	2.2 ft	75	4.0	No	No	0.1	2	4	
S5	5	0.3	2.4 ft	75	3.85	No	No	0.2	2	5	
S6	6	0.3	2.6 ft	77	3.8	No	No	0.3	3/2	8/9	
S7	7	0.3	2.5 ft	77	3.9	No	No	0.3	2	10	

OCI

Hydro camera # 298

Aerial photo Filgrin Cam

117 → 123