

Date & Time: 3-21-2014 1350

Location: PRA 114

Camera: TI-SWG-GAR0-1

Crew: BT, MP, RK

Weather: clear

GPS Unit: PDX

Comments:

(A)	(B)	(D)	(E)	(F)	(G)	(H)	(I)	(J)	(K)	(L)	(M)
Sample #	GPS Point #	Snow Depth (ft)	Ice Thickness (ft)	Top of Ice to Bed Distance (ft)	Flow Depth (F-E) (ft)	Frazil Ice Present?	Anchor Ice Present?	Freeboard Height (ft)	Camera Height above Bed (ft)	Video #	Comments / Bed Description
S1	1	± 8"	2.9	121	7.2	N	N	1.1	4	139	
S2	2	8	3.0	119	6.9	N	N	1.3	4	140	
S3	3	8	3.0	118	6.8	N	N	1.3	4	141	
S4	4	8	3.0	123	7.3	N	N	1.1	4	142	
S5	5	8	3.0	121	7.1	N	N	1.3	4	143	
S6	6	8	3.2	116	6.5	N	N	1.3	4	144	
S7	7	8	3.3	112	7.0	N	N	1.2	4	145	
S8	8	8	3.4	111	6.7	N	N	1.3	4	146	
S9	9	8	3.3	123	7.0	N	N	1.3	4	147, 148	
S10	10	8	3.4	124	6.9	N	N	1.4	4	149, 150	

Photo Back up #

Kilgren Camera # 311

Sheet 2 of 2

Aerial photo camera 1

515
516
517

QC1 BUP

Plot BUP Kilger Census # 312 3/21/14