

Date & Time: 3-21-2014 1115

Crew: BT, MP, RK

Sheet 1 of 2

Location: PRAVIA

Weather: Clear

Camera: TT-SWG-Gopro-1

GPS Unit: PDX

Comments: videos 119-121 checking 2 holes river left with too much frazil present in image to sample
 1 Photo # 504 Right bank looking left / Klygna camera Photo # 132 left bank looking right # 133 left bank looking left # 134 left bank looking left

(A) Sample #	(B) GPS Point #	(D) Snow Depth (ft)	(E) Ice Thickness (ft)	(F) Top of Ice to Bed Distance (ft)	(G) Flow Depth (F-E) (ft)	(H) Frazil Ice Present?	(I) Anchor Ice Present?	(J) Freeboard Height (ft)	(K) Camera Height above Bed (ft)	(L) Video #	(M) Comments / Bed Description
S1	1	0.5	2.2	63	3.1	Y	N	0.2	3	122	
S2	2	0.5	2.3	65	3.1	Y	N	0.2	3	123	124
S3	3	0.5	2.1	65	3.3	Y	N	0.2	3	125	123 - camera note
S4	4	0.5	2.3	64	3.0	Y	N	0.2	3	126	124 - note
S5	5	0.5	2.3	65	3.1	Y	N	0.2	3	127	
S6	6	0.5	2.2	64	3.1	Y	N	0.2	3	128	
S7	7	0.5	2.4	72	3.6	Y	N	0.5	3	129	
S8	8	0.5	2.7	67	2.9	Y	N	0.2	3	130	
S9	9	0.5	2.7	67	2.9	Y	N	0.1	3	131, 132	
S10	10	0.5	2.7	64	2.6	Y	N	0.2	3	133	
S11	11	0.5	2.6	61	2.5	Y	N	0.2	3	134	
S12	12	0.5	2.5	60	2.5	Y	N	0.1	3	135, 136	
S13	13	0.5	2.5	63	2.8	Y	N	0.2	3	137	

QC1

Photo Back up # Klygna Camera #309

Sheet 2 of 2

Aerial photo camera 1
518, 519, 520

RL RE

pls Bwp Kilgus ~~sement~~ # 310

3/21/14