

Date & Time: 3-23-2014 1100

Crew: BK, MP, BT

Sheet 1 of 2

Location: PRM 129.6

Weather: clear

Camera: # SW6 - GoPro - 1

GPS Unit: PDX

Comments: Camera 1 Photo #504 Left side over looking right #505 center line looking left  
#506 center line looking left #507 right side down looking left

(A) Sample #	(B) GPS Point #	(D) Snow Depth (ft)	(E) Ice Thickness (ft)	(F) Top of Ice to Bed Distance (ft)	(G) Flow Depth (F - E) (ft)	(H) Frazil Ice Present?	(I) Anchor Ice Present?	(J) Freeboard Height (ft)	(K) Camera Height above Bed (ft)	(L) Video #	(M) Comments / Bed Description
S1	1	10.7	3.5	104	5.2	Y	N	0.2	4	119	
S2	2	10	2.6	104	6.1	Y	N	0.2	4	120	
S3	3	1	3.9	101	4.5	Y	N	0.0	4	121	
S4	4	1	4.2	102	4.3	Y	N	0.0	4	122	
S5	5	2	3.5	105	5.3	Y	N	0.1	4	123	
S6	6	8	3.7	100	4.6	Y	N	0.3	4	124	
S7	7	4	3.5	107	5.4	Y	N	0.0	4	125	
S8	8	2	3.8	103	4.8	Y	N	0.0	4	126	
S9	9	2	3.2	106	5.6	Y	N	0.1	4	127	
S10	10	8	3.7	104	5.0	Y	N	0.2	4	128	
S11	11	6	3.4	108	5.6	Y	N	0.1	4	129	
S12	12	2	3.8	109	5.3	Y	N	0.0	4	130	
S13	13	4	3.5	105	5.3	Y	N	0.0	4	131, 132	1st video stop touched ice ends
S14	14	8	3.7	108	5.3	Y	N	0.3	4	133	
S15	15	10	2.6	106	6.2	Y	N	0.2	4	134	
S16	16	2	3.7	110	5.5	Y	N	0.1	4	135	


Photo Back up # Kilgus Camera # 305

QC 1 *[Signature]*

Photo B & P

Kilgus camera # 306

3/23/14



holes spaced 8-10'

- # 175
- 176
- 177
- 178
- 179
- 180
- 181


Aerial Photos of moles  
Kilgus camera  
Photos

QC 1 *[Signature]*

Photo B & P

Kilgus camera # 306

3/23/14



holes spaced 8-10'

- # 175
- 176
- 177
- 178
- 179
- 180
- 181

Aerial Photos of holes  
Kilgus camera  
Photos