WETLAND DETERMINATION DATA FORM - Alaska Region

Project/Site: Susitna-Watana Hydroelectric Project | Borough/City: Denali Borough | Sampling Date: 06-Aug-12

Applicant/Owner: Alaska Energy Authority | Sampling Point: **SW12_T16_08**

Investigator(s): SLI, KMK | Landform (hillside, terrace, hummocks etc.): Hillside

Local relief (concave, convex, none): hummocky | Slope: % / 12.8 ° | Elevation: 790

Subregion : Interior Alaska Mountains | Lat.: 63.4271198674 | Long.: -148.615068551 | Datum: NAD83

Soil Map Unit Name: | **NWI classification:** Upland

Are climatic/hydrologic conditions on the site typical for this time of year? Yes ◉ No ○ (If no, explain in Remarks.)

Are Vegetation ☑ , Soil ☐ , or Hydrology ☐ significantly disturbed? Are "Normal Circumstances" present? Yes ◉ No ○

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS - Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present? Yes ◉ No ○

Hydric Soil Present? Yes ○ No ◉

Wetland Hydrology Present? Yes ○ No ◉

Is the Sampled Area within a Wetland? Yes ○ No ◉

Remarks: picea woodland - understory alternates between tall alnus and low salix-graminoid communities, plot spans both. on hike from SW12_T16_07 to here, walked through substantial picmar wetland, appeared to be seep at topo break.

VEGETATION - Use scientific names of plants. List all species in the plot.

Tree Stratum	Absolute % Cover	Dominant Species?	Indicator Status
1. Picea glauca	10	☑	FACU
2.	0	☐	
3.	0	☐	
4.	0	☐	
5.	0	☐	
Total Cover:	10		

50% of Total Cover: 5 | 20% of Total Cover: 2

Sapling/Shrub Stratum	Absolute % Cover	Dominant Species?	Indicator Status
1. Salix pulchra	20	☑	FACW
2. Alnus viridis	30	☑	FAC
3. Vaccinium uliginosum	10	☐	FAC
4. Vaccinium vitis-idaea	0.1	☐	FAC
5. Spiraea stevenii	5	☐	FACU
6. Picea glauca	3	☐	FACU
7. Ribes triste	2	☐	FAC
8. Linnaea borealis	2	☐	FACU
9.	0	☐	
10.	0	☐	
Total Cover:	72.1		

50% of Total Cover: 36.05 | 20% of Total Cover: 14.42

Herb Stratum	Absolute % Cover	Dominant Species?	Indicator Status
1. Calamagrostis canadensis	10	☑	FAC
2. Cornus canadensis	1	☐	FACU
3. Lycopodium clavatum	3	☐	FACU
4. Mertensia paniculata	3	☐	FACU
5. Aconitum delphiniifolium	0.1	☐	FAC
6. Boykinia richardsonii	11	☑	UPL
7. Polemonium acutiflorum	1	☐	FAC
8. Bistorta plumosa	1	☐	FACU
9. Poa interior	0.1	☐	FAC
10. Luzula parviflora	0.1	☐	FAC
Total Cover:	30.3		

50% of Total Cover: 15.15 | 20% of Total Cover: 6.06

Dominance Test worksheet:

Number of Dominant Species That are OBL, FACW, or FAC: 3 (A)

Total Number of Dominant Species Across All Strata: 5 (B)

Percent of dominant Species That Are OBL, FACW, or FAC: 60.0% (A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply by:	
OBL Species	0	x 1 =	0
FACW Species	20	x 2 =	40
FAC Species	####:	x 3 =	160.2
FACU Species	28	x 4 =	112
UPL Species	11	x 5 =	55
Column Totals:	112.4	(A)	367.2 (B)

Prevalence Index = B/A = 3.267

Hydrophytic Vegetation Indicators:

☑ Dominance Test is > 50%

☐ Prevalence Index is ≤3.0

☐ Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

☐ Problematic Hydrophytic Vegetation[1] (Explain)

[1] Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Plot size (radius, or length x width) 10m

% Cover of Wetland Bryophytes (Where applicable)

% Bare Ground

Total Cover of Bryophytes

Hydrophytic Vegetation Present? Yes ◉ No ○

Remarks: 1% carbig

SOIL

Sampling Point: SW12_T16_08

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators)

Depth (inches)	Matrix Color (moist)		%	Redox Features Color (moist)		%	Type [1]	Loc [2]	Texture	Remarks
0-2									Fibric Organics	
2-4									Hemic Organics	
4-4.5									Sapric Organics	
4.5-16	7.5YR	3/2	90						Sandy Loam	10% sapric organic lenses

[1] Type: C=Concentration. D=Depletion. RM=Reduced Matrix [2] Location: PL=Pore Lining. RC=Root Channel. M=Matrix

Hydric Soil Indicators:

- ☐ Histosol or Histel (A1)
- ☐ Histic Epipedon (A2)
- ☐ Hydrogen Sulfide (A4)
- ☐ Thick Dark Surface (A12)
- ☐ Alaska Gleyed (A13)
- ☐ Alaska Redox (A14)
- ☐ Alaska Gleyed Pores (A15)

Indicators for Problematic Hydric Soils:[3]

- ☐ Alaska Color Change (TA4)[4]
- ☐ Alaska Alpine swales (TA5)
- ☐ Alaska Redox With 2.5Y Hue
- ☐ Alaska Gleyed Without Hue 5Y or Redder Underlying Layer
- ☐ Other (Explain in Remarks)

[3] One indicator of hydrophytic vegetation, one primary indicator of wetland hydrology, and an appropriate landscape position must be present

[4] Give details of color change in Remarks

Restrictive Layer (if present):
Type:
Depth (inches):

Hydric Soil Present? Yes ○ No ◉

Remarks:
no hydric soil indicators

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (any one is sufficient)

- ☐ Surface Water (A1)
- ☐ High Water Table (A2)
- ☐ Saturation (A3)
- ☐ Water Marks (B1)
- ☐ Sediment Deposits (B2)
- ☐ Drift Deposits (B3)
- ☐ Algal Mat or Crust (B4)
- ☐ Iron Deposits (B5)
- ☐ Surface Soil Cracks (B6)
- ☐ Inundation Visible on Aerial Imagery (B7)
- ☐ Sparsely Vegetated Concave Surface (B8)
- ☐ Marl Deposits (B15)
- ☐ Hydrogen Sulfide Odor (C1)
- ☐ Dry-Season Water Table (C2)
- ☐ Other (Explain in Remarks)

Secondary Indicators (two or more are required)

- ☐ Water Stained Leaves (B9)
- ☐ Drainage Patterns (B10)
- ☐ Oxidized Rhizospheres along Living Roots (C3)
- ☐ Presence of Reduced Iron (C4)
- ☐ Salt Deposits (C5)
- ☐ Stunted or Stressed Plants (D1)
- ☐ Geomorphic Position (D2)
- ☐ Shallow Aquitard (D3)
- ☐ Microtopographic Relief (D4)
- ☐ FAC-neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ○	No ◉	Depth (inches):
Water Table Present?	Yes ○	No ◉	Depth (inches):
Saturation Present? (includes capillary fringe)	Yes ○	No ◉	Depth (inches):

Wetland Hydrology Present? Yes ○ No ◉

Describe Recorded Data (stream gauge, monitor well, aerial photos, previous inspection) if available:

Remarks:
no wetland hydrology indicators