WETLAND DETERMINATION DATA FORM - Alaska Region

Project/Site: Susitna-Watana Hydroelectric Project | Borough/City: Matanuska-Susitna Borough | Sampling Date: 05-Jul-13

Applicant/Owner: Alaska Energy Authority | Sampling Point: **SW13_T105_01**

Investigator(s): JER | Landform (hillside, terrace, hummocks etc.): Swale

Local relief (concave, convex, none): concave | Slope: % / 1.1 ° | Elevation: 773

Subregion : Interior Alaska Mountains | Lat.: 62.7576868531 | Long.: -147.918929099 | Datum: NAD83

Soil Map Unit Name: | **NWI classification: PSS1E**

Are climatic/hydrologic conditions on the site typical for this time of year? Yes ◉ No ○ (If no, explain in Remarks.)

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ significantly disturbed? Are "Normal Circumstances" present? Yes ◉ No ○

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS - Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present? Yes ◉ No ○

Hydric Soil Present? Yes ◉ No ○

Wetland Hydrology Present? Yes ◉ No ○

Is the Sampled Area within a Wetland? **Yes ◉ No ○**

Remarks: upper swale with many rivulets and pockets of water. moose browse, one bull on transect, several groups [6-12] caribou. slcw

VEGETATION - Use scientific names of plants. List all species in the plot.

Tree Stratum	Absolute % Cover	Dominant Species?	Indicator Status
1.	0	☐	
2.	0	☐	
3.	0	☐	
4.	0	☐	
5.	0	☐	
Total Cover:	0		

50% of Total Cover: 0 | 20% of Total Cover: 0

Sapling/Shrub Stratum			
1. Salix pulchra	45	☑	FACW
2. Salix richardsonii	25	☑	FACW
3. Vaccinium uliginosum	15	☐	FAC
4. Salix arbusculoides	10	☐	FACW
5.	0	☐	
6.	0	☐	
7.	0	☐	
8.	0	☐	
9.	0	☐	
10.	0	☐	
Total Cover:	95		

50% of Total Cover: 47.5 | 20% of Total Cover: 19

Herb Stratum			
1. Comarum palustre	15	☑	OBL
2. Carex membranacea	8	☑	FACW
3. Calamagrostis canadensis	5	☐	FAC
4. Carex aquatilis	3	☐	OBL
5. Rumex arcticus	1	☐	FAC
6. Trientalis europaea	1	☐	FACU
7. Viola palustris (IAM)	1	☐	FAC
8.	0	☐	
9.	0	☐	
10.	0	☐	
Total Cover:	34		

50% of Total Cover: 17 | 20% of Total Cover: 6.8

Dominance Test worksheet:

Number of Dominant Species That are OBL, FACW, or FAC: 4 (A)

Total Number of Dominant Species Across All Strata: 4 (B)

Percent of dominant Species That Are OBL, FACW, or FAC: 100.0% (A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply by:	
OBL Species	18	x 1 =	18
FACW Species	88	x 2 =	176
FAC Species	22	x 3 =	66
FACU Species	1	x 4 =	4
UPL Species	0	x 5 =	0
Column Totals:	129 (A)		264 (B)

Prevalence Index = B/A = 2.047

Hydrophytic Vegetation Indicators:

☑ Dominance Test is > 50%

☑ Prevalence Index is ≤3.0

☐ Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

☐ Problematic Hydrophytic Vegetation[1] (Explain)

[1] Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Plot size (radius, or length x width) 10m

% Cover of Wetland Bryophytes (Where applicable)

% Bare Ground 1

Total Cover of Bryophytes 40

Hydrophytic Vegetation Present? **Yes ◉ No ○**

Remarks: sphag 30, mnium-like 15, water 10

SOIL

Sampling Point: SW13_T105_01

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators)

Depth (inches)	Matrix Color (moist)		%	Redox Features Color (moist)		%	Type[1]	Loc[2]	Texture	Remarks
0-3			95						Fibric Organics	oi w SiSa
3-5	10YR	3/2	100						Silt Loam	org mixed in
5-8	5Y	4/1	80	10YR	4/4	20	C	PL	Silt Loam	
8-9	10YR	2/1	100						Fibric Organics	Fibric Organics
9-12	2.5Y	3/1	100						Sandy Loam	high organic content, chunks

[1] Type: C=Concentration. D=Depletion. RM=Reduced Matrix [2] Location: PL=Pore Lining. RC=Root Channel. M=Matrix

Hydric Soil Indicators:

- ☐ Histosol or Histel (A1)
- ☐ Histic Epipedon (A2)
- ☑ Hydrogen Sulfide (A4)
- ☐ Thick Dark Surface (A12)
- ☐ Alaska Gleyed (A13)
- ☑ Alaska Redox (A14)
- ☐ Alaska Gleyed Pores (A15)

Indicators for Problematic Hydric Soils:[3]

- ☐ Alaska Color Change (TA4)[4]
- ☐ Alaska Alpine swales (TA5)
- ☐ Alaska Redox With 2.5Y Hue
- ☐ Alaska Gleyed Without Hue 5Y or Redder Underlying Layer
- ☐ Other (Explain in Remarks)

[3] One indicator of hydrophytic vegetation, one primary indicator of wetland hydrology, and an appropriate landscape position must be present

[4] Give details of color change in Remarks

Restrictive Layer (if present):
Type: frost
Depth (inches): 12

Hydric Soil Present? Yes ◉ No ○

Remarks:

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (any one is sufficient)

- ☑ Surface Water (A1)
- ☑ High Water Table (A2)
- ☑ Saturation (A3)
- ☐ Water Marks (B1)
- ☑ Sediment Deposits (B2)
- ☐ Drift Deposits (B3)
- ☐ Algal Mat or Crust (B4)
- ☑ Iron Deposits (B5)
- ☐ Surface Soil Cracks (B6)
- ☐ Inundation Visible on Aerial Imagery (B7)
- ☐ Sparsely Vegetated Concave Surface (B8)
- ☐ Marl Deposits (B15)
- ☑ Hydrogen Sulfide Odor (C1)
- ☐ Dry-Season Water Table (C2)
- ☐ Other (Explain in Remarks)

Secondary Indicators (two or more are required)

- ☑ Water Stained Leaves (B9)
- ☐ Drainage Patterns (B10)
- ☐ Oxidized Rhizospheres along Living Roots (C3)
- ☐ Presence of Reduced Iron (C4)
- ☐ Salt Deposits (C5)
- ☐ Stunted or Stressed Plants (D1)
- ☑ Geomorphic Position (D2)
- ☑ Shallow Aquitard (D3)
- ☐ Microtopographic Relief (D4)
- ☑ FAC-neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ○	No ◉	Depth (inches):
Water Table Present?	Yes ◉	No ○	Depth (inches): 8
Saturation Present? (includes capillary fringe)	Yes ◉	No ○	Depth (inches): 3

Wetland Hydrology Present? Yes ◉ No ○

Describe Recorded Data (stream gauge, monitor well, aerial photos, previous inspection) if available:

Remarks:
patches standing water, rivulets running thru plot