WETLAND DETERMINATION DATA FORM - Alaska Region

Project/Site: Susitna-Watana Hydroelectric Project | Borough/City: Matanuska-Susitna Borough | Sampling Date: 31-Jul-13

Applicant/Owner: Alaska Energy Authority | Sampling Point: **SW13_T154_02**

Investigator(s): BAB | Landform (hillside, terrace, hummocks etc.): drainage

Local relief (concave, convex, none): hummocky | Slope: % / 13.2 ° | Elevation: 113

Subregion : Interior Alaska Mountains | Lat.: 63.2394504552 | Long.: -148.369465722 | Datum: NAD83

Soil Map Unit Name: | **NWI classification:** Upland

Are climatic/hydrologic conditions on the site typical for this time of year? Yes ◉ No ○ (If no, explain in Remarks.)

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ significantly disturbed? Are "Normal Circumstances" present? Yes ◉ No ○

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS - Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ◉ No ○	**Is the Sampled Area within a Wetland?** Yes ○ No ◉
Hydric Soil Present?	Yes ○ No ◉	
Wetland Hydrology Present?	Yes ○ No ◉	

Remarks: Wide >30 feet drainage gently sloping

VEGETATION - Use scientific names of plants. List all species in the plot.

	Tree Stratum	Absolute % Cover	Dominant Species?	Indicator Status
1.		0	☐	
2.		0	☐	
3.		0	☐	
4.		0	☐	
5.		0	☐	
	Total Cover:	0		

50% of Total Cover: 0 | 20% of Total Cover: 0

	Sapling/Shrub Stratum			
1.	Salix pulchra	30	☑	FACW
2.	Spiraea stevenii	10	☑	FACU
3.	Empetrum nigrum	5	☐	FAC
4.	Vaccinium uliginosum	2	☐	FAC
5.	Cassiope tetragona	1	☐	FACU
6.		0	☐	
7.		0	☐	
8.		0	☐	
9.		0	☐	
10.		0	☐	
	Total Cover:	48		

50% of Total Cover: 24 | 20% of Total Cover: 9.6

	Herb Stratum			
1.	Festuca altaica	8	☑	FAC
2.	Sanguisorba canadensis	5	☑	FACW
3.	Antennaria friesiana	3	☑	UPL
4.	Chamaenerion angustifolium	3	☑	FACU
5.	Luzula parviflora	2	☐	FAC
6.	Rubus arcticus (IAM)	2	☐	FACU
7.	Artemisia norvegica	2	☐	FACU
8.	Carex bigelowii	2	☐	FAC
9.	Sibbaldia procumbens	1	☐	FACU
10.	Rhodiola integrifolia	1	☐	FAC
	Total Cover:	29		

50% of Total Cover: 14.5 | 20% of Total Cover: 5.8

Dominance Test worksheet:

Number of Dominant Species That are OBL, FACW, or FAC: 3 (A)

Total Number of Dominant Species Across All Strata: 6 (B)

Percent of dominant Species That Are OBL, FACW, or FAC: 50.0% (A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply by:	
OBL Species	0	x 1 =	0
FACW Species	35	x 2 =	70
FAC Species	20	x 3 =	60
FACU Species	19	x 4 =	76
UPL Species	3	x 5 =	15
Column Totals:	77 (A)		221 (B)

Prevalence Index = B/A = 2.870

Hydrophytic Vegetation Indicators:

- ☐ Dominance Test is > 50%
- ☑ Prevalence Index is ≤3.0
- ☐ Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)
- ☐ Problematic Hydrophytic Vegetation[1] (Explain)

[1] Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Plot size (radius, or length x width) 10m

% Cover of Wetland Bryophytes (Where applicable)

% Bare Ground

Total Cover of Bryophytes 20

Hydrophytic Vegetation Present? Yes ◉ No ○

Remarks: trace stelon, Gentiana glauca, aconitum delphiniifolium caratr 1.0

SOIL

Sampling Point: SW13_T154_02

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators)

Depth (inches)	Matrix Color (moist)		Matrix %	Redox Features Color (moist)		Redox Features %	Redox Features Type[1]	Redox Features Loc[2]	Texture	Remarks
0-1			100						Fibric Organics	
1-6			100						Hemic Organics	lots of ang to rounded grvl& cobbles
6-20	10YR	3/2	100						Silt Loam	lots of ang to rounded gravel and cobbles

[1] Type: C=Concentration. D=Depletion. RM=Reduced Matrix [2] Location: PL=Pore Lining. RC=Root Channel. M=Matrix

Hydric Soil Indicators:

- ☐ Histosol or Histel (A1)
- ☐ Histic Epipedon (A2)
- ☐ Hydrogen Sulfide (A4)
- ☐ Thick Dark Surface (A12)
- ☐ Alaska Gleyed (A13)
- ☐ Alaska Redox (A14)
- ☐ Alaska Gleyed Pores (A15)

Indicators for Problematic Hydric Soils:[3]

- ☐ Alaska Color Change (TA4)[4]
- ☐ Alaska Alpine swales (TA5)
- ☐ Alaska Redox With 2.5Y Hue
- ☐ Alaska Gleyed Without Hue 5Y or Redder Underlying Layer
- ☐ Other (Explain in Remarks)

[3] One indicator of hydrophytic vegetation, one primary indicator of wetland hydrology, and an appropriate landscape position must be present

[4] Give details of color change in Remarks

Restrictive Layer (if present):
Type:
Depth (inches):

Hydric Soil Present? Yes ○ No ◉

Remarks:
no hydric soil indicators observed

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (any one is sufficient)

- ☐ Surface Water (A1)
- ☐ High Water Table (A2)
- ☐ Saturation (A3)
- ☐ Water Marks (B1)
- ☐ Sediment Deposits (B2)
- ☐ Drift Deposits (B3)
- ☐ Algal Mat or Crust (B4)
- ☐ Iron Deposits (B5)
- ☐ Surface Soil Cracks (B6)
- ☐ Inundation Visible on Aerial Imagery (B7)
- ☐ Sparsely Vegetated Concave Surface (B8)
- ☐ Marl Deposits (B15)
- ☐ Hydrogen Sulfide Odor (C1)
- ☐ Dry-Season Water Table (C2)
- ☐ Other (Explain in Remarks)

Secondary Indicators (two or more are required)

- ☐ Water Stained Leaves (B9)
- ☐ Drainage Patterns (B10)
- ☐ Oxidized Rhizospheres along Living Roots (C3)
- ☐ Presence of Reduced Iron (C4)
- ☐ Salt Deposits (C5)
- ☐ Stunted or Stressed Plants (D1)
- ☑ Geomorphic Position (D2)
- ☐ Shallow Aquitard (D3)
- ☐ Microtopographic Relief (D4)
- ☐ FAC-neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ○	No ◉	Depth (inches):
Water Table Present?	Yes ○	No ◉	Depth (inches):
Saturation Present? (includes capillary fringe)	Yes ○	No ◉	Depth (inches):

Wetland Hydrology Present? Yes ○ No ◉

Describe Recorded Data (stream gauge, monitor well, aerial photos, previous inspection) if available:

Remarks:
only one secondary hydrology indicator observed