WETLAND DETERMINATION DATA FORM - Alaska Region

Project/Site: Susitna-Watana Hydroelectric Project | Borough/City: Matanuska-Susitna Borough | Sampling Date: 10-Jul-13

Applicant/Owner: Alaska Energy Authority | Sampling Point: **SW13_T184_04**

Investigator(s): JGK | Landform (hillside, terrace, hummocks etc.): Hillside

Local relief (concave, convex, none): hummocky | Slope: % / 10.0 ° | Elevation: 678

Subregion : Interior Alaska Mountains | Lat.: 62.8494701395 | Long.: -148.574418069 | Datum: NAD83

Soil Map Unit Name: | **NWI classification:** Upland

Are climatic/hydrologic conditions on the site typical for this time of year? Yes ◉ No ○ (If no, explain in Remarks.)

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ significantly disturbed? Are "Normal Circumstances" present? Yes ◉ No ○

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS - Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ◉ No ○	**Is the Sampled Area within a Wetland?** Yes ○ No ◉
Hydric Soil Present?	Yes ○ No ◉	
Wetland Hydrology Present?	Yes ○ No ◉	

Remarks:

VEGETATION - Use scientific names of plants. List all species in the plot.

Tree Stratum	Absolute % Cover	Dominant Species?	Indicator Status
1. Picea glauca	7	☑	FACU
2. Betula neoalaskana	3	☑	FACU
3.	0	☐	
4.	0	☐	
5.	0	☐	
Total Cover:	10		

50% of Total Cover: 5 | 20% of Total Cover: 2

Sapling/Shrub Stratum			
1. Alnus viridis	50	☑	FAC
2. Ribes triste	15	☑	FAC
3. Vaccinium vitis-idaea	3	☐	FAC
4. Linnaea borealis	2	☐	FACU
5.	0	☐	
6.	0	☐	
7.	0	☐	
8.	0	☐	
9.	0	☐	
10.	0	☐	
Total Cover:	70		

50% of Total Cover: 35 | 20% of Total Cover: 14

Herb Stratum			
1. Cornus suecica	3	☐	FAC
2. Orthilia secunda	0.1	☐	FACU
3. Spinulum annotinum	5	☐	FACU
4. Calamagrostis canadensis	40	☑	FAC
5. Mertensia paniculata	5	☐	FACU
6. Sanguisorba officinalis	10	☐	FACW
7. Dryopteris expansa	2	☐	FACU
8. Equisetum sylvaticum	25	☑	FAC
9. Equisetum arvense	0.1	☐	FAC
10. Viola palustris (IAM)	0.1	☐	FAC
Total Cover:	90.3		

50% of Total Cover: 45.15 | 20% of Total Cover: 18.06

Dominance Test worksheet:

Number of Dominant Species That are OBL, FACW, or FAC: 4 (A)

Total Number of Dominant Species Across All Strata: 6 (B)

Percent of dominant Species That Are OBL, FACW, or FAC: 66.7% (A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply by:	
OBL Species	0	x 1 =	0
FACW Species	10	x 2 =	20
FAC Species	136.2	x 3 =	408.6
FACU Species	24.1	x 4 =	96.40
UPL Species	0	x 5 =	0
Column Totals:	170.3 (A)		525.0 (B)

Prevalence Index = B/A = 3.083

Hydrophytic Vegetation Indicators:

☑ Dominance Test is > 50%

☐ Prevalence Index is ≤3.0

☐ Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

☐ Problematic Hydrophytic Vegetation[1] (Explain)

[1] Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Plot size (radius, or length x width) 10m

% Cover of Wetland Bryophytes (Where applicable) 0

% Bare Ground 5

Total Cover of Bryophytes 20

Hydrophytic Vegetation Present? Yes ◉ No ○

Remarks: Tr trientalis valcap delgla

SOIL

Sampling Point: SW13_T184_04

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators)

Depth (inches)	Matrix Color (moist)		%	Redox Features Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0-7								Fibric Organics	
7-8								Sapric Organics	Charcoal layer
8-11	7.5YR	3/2	100					Sandy Silt Loam	Some angular cobbles
11-14								Angular cobbles with some silt	Cobbles 3-5 in diameter

[1] Type: C=Concentration. D=Depletion. RM=Reduced Matrix [2] Location: PL=Pore Lining. RC=Root Channel. M=Matrix

Hydric Soil Indicators:

- ☐ Histosol or Histel (A1)
- ☐ Histic Epipedon (A2)
- ☐ Hydrogen Sulfide (A4)
- ☐ Thick Dark Surface (A12)
- ☐ Alaska Gleyed (A13)
- ☐ Alaska Redox (A14)
- ☐ Alaska Gleyed Pores (A15)

Indicators for Problematic Hydric Soils:[3]

- ☐ Alaska Color Change (TA4)[4]
- ☐ Alaska Alpine swales (TA5)
- ☐ Alaska Redox With 2.5Y Hue
- ☐ Alaska Gleyed Without Hue 5Y or Redder Underlying Layer
- ☐ Other (Explain in Remarks)

[3] One indicator of hydrophytic vegetation, one primary indicator of wetland hydrology, and an appropriate landscape position must be present

[4] Give details of color change in Remarks

Restrictive Layer (if present):
Type:
Depth (inches):

Hydric Soil Present? Yes ○ No ◉

Remarks:
cannot apply A2 as soils are not saturated, no secondary indicators to infer saturation.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (any one is sufficient)

- ☐ Surface Water (A1)
- ☐ High Water Table (A2)
- ☐ Saturation (A3)
- ☐ Water Marks (B1)
- ☐ Sediment Deposits (B2)
- ☐ Drift Deposits (B3)
- ☐ Algal Mat or Crust (B4)
- ☐ Iron Deposits (B5)
- ☐ Surface Soil Cracks (B6)
- ☐ Inundation Visible on Aerial Imagery (B7)
- ☐ Sparsely Vegetated Concave Surface (B8)
- ☐ Marl Deposits (B15)
- ☐ Hydrogen Sulfide Odor (C1)
- ☐ Dry-Season Water Table (C2)
- ☐ Other (Explain in Remarks)

Secondary Indicators (two or more are required)

- ☐ Water Stained Leaves (B9)
- ☐ Drainage Patterns (B10)
- ☐ Oxidized Rhizospheres along Living Roots (C3)
- ☐ Presence of Reduced Iron (C4)
- ☐ Salt Deposits (C5)
- ☐ Stunted or Stressed Plants (D1)
- ☐ Geomorphic Position (D2)
- ☐ Shallow Aquitard (D3)
- ☐ Microtopographic Relief (D4)
- ☐ FAC-neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ○	No ◉	Depth (inches):
Water Table Present?	Yes ○	No ◉	Depth (inches):
Saturation Present? (includes capillary fringe)	Yes ○	No ◉	Depth (inches):

Wetland Hydrology Present? Yes ○ No ◉

Describe Recorded Data (stream gauge, monitor well, aerial photos, previous inspection) if available:

Remarks: