## WETLAND DETERMINATION DATA FORM - Alaska Region

Project/Site: Susitna-Watana Hydroelectric Project | Borough/City: Matanuska-Susitna Borough | Sampling Date: 11-Jul-13

Applicant/Owner: Alaska Energy Authority | Sampling Point: **SW13_T190_02**

Investigator(s): JGK | Landform (hillside, terrace, hummocks etc.): Saddle

Local relief (concave, convex, none): hummocky | Slope: % / 4.2 ° | Elevation: 102

Subregion : Interior Alaska Mountains | Lat.: 62.9497513773 | Long.: -148.219095349 | Datum: NAD83

Soil Map Unit Name: | **NWI classification: PSS1B**

Are climatic/hydrologic conditions on the site typical for this time of year? Yes ◉ No ○ (If no, explain in Remarks.)

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ significantly disturbed? Are "Normal Circumstances" present? Yes ◉ No ○

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ naturally problematic? (If needed, explain any answers in Remarks.)

**SUMMARY OF FINDINGS -** Attach site map showing sampling point locations, transects, important features, etc.

| | | |
|---|---|---|
| Hydrophytic Vegetation Present? | Yes ◉ No ○ | **Is the Sampled Area within a Wetland?** **Yes ◉ No ○** |
| Hydric Soil Present? | Yes ◉ No ○ | |
| Wetland Hydrology Present? | Yes ◉ No ○ | |

Remarks:

**VEGETATION -** Use scientific names of plants. List all species in the plot.

| | Tree Stratum | Absolute % Cover | Dominant Species? | Indicator Status |
|---|---|---|---|---|
| 1. | | 0 | ☐ | |
| 2. | | 0 | ☐ | |
| 3. | | 0 | ☐ | |
| 4. | | 0 | ☐ | |
| 5. | | 0 | ☐ | |
| | **Total Cover:** | 0 | | |

50% of Total Cover: 0 | 20% of Total Cover: 0

| | Sapling/Shrub Stratum | | | |
|---|---|---|---|---|
| 1. | Vaccinium uliginosum | 20 | ☑ | FAC |
| 2. | Vaccinium vitis-idaea | 3 | ☐ | FAC |
| 3. | Empetrum nigrum | 15 | ☐ | FAC |
| 4. | Betula nana | 35 | ☑ | FAC |
| 5. | Salix reticulata | 10 | ☐ | FAC |
| 6. | Salix pulchra | 3 | ☐ | FACW |
| 7. | Arctous ruber | 2 | ☐ | FAC |
| 8. | Dryas ajanensis | 3 | ☐ | UPL |
| 9. | Picea glauca | 0.1 | ☐ | FACU |
| 10. | Betula neoalaskana | 0.1 | ☐ | FACU |
| | **Total Cover:** | 91.2 | | |

50% of Total Cover: 45.6 | 20% of Total Cover: 18.24

| | Herb Stratum | | | |
|---|---|---|---|---|
| 1. | Pedicularis labradorica | 2 | ☐ | FACW |
| 2. | Carex bigelowii | 20 | ☑ | FAC |
| 3. | Anthoxanthum monticola ssp. alpinum | 1 | ☐ | UPL |
| 4. | Bistorta plumosa | 3 | ☐ | FACU |
| 5. | Poa glauca | 2 | ☐ | UPL |
| 6. | Orthilia secunda | 0.1 | ☐ | FACU |
| 7. | | 0 | ☐ | |
| 8. | | 0 | ☐ | |
| 9. | | 0 | ☐ | |
| 10. | | 0 | ☐ | |
| | **Total Cover:** | 28.1 | | |

50% of Total Cover: 14.05 | 20% of Total Cover: 5.62

**Dominance Test worksheet:**

Number of Dominant Species That are OBL, FACW, or FAC: 3 (A)

Total Number of Dominant Species Across All Strata: 3 (B)

Percent of dominant Species That Are OBL, FACW, or FAC: 100.0% (A/B)

**Prevalence Index worksheet:**

| Total % Cover of: | | Multiply by: | |
|---|---|---|---|
| OBL Species | 0 | x 1 = | 0 |
| FACW Species | 5 | x 2 = | 10 |
| FAC Species | 105 | x 3 = | 315 |
| FACU Species | 4.3 | x 4 = | 17.2 |
| UPL Species | 5 | x 5 = | 25 |
| Column Totals: | 119.3 (A) | | 367.2 (B) |

Prevalence Index = B/A = 3.078

**Hydrophytic Vegetation Indicators:**

- ☑ Dominance Test is > 50%
- ☐ Prevalence Index is ≤3.0
- ☐ Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)
- ☑ Problematic Hydrophytic Vegetation[1] (Explain)

[1] Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Plot size (radius, or length x width) 10m

% Cover of Wetland Bryophytes (Where applicable) 5

% Bare Ground 2

Total Cover of Bryophytes 60

**Hydrophytic Vegetation Present?** **Yes ◉ No ○**

Remarks: Lichen 5. Trace Stellaria sp. Trace picgla shrub is krummholtz.
betnan is mostly dwarf strata

## SOIL

**Sampling Point: SW13_T190_02**

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators)

| Depth (inches) | Matrix Color (moist) | | % | Redox Features Color (moist) | | % | Type[1] | Loc[2] | Texture | Remarks |
|---|---|---|---|---|---|---|---|---|---|---|
| 0-2 | | | 100 | | | | | | Fibric Organics | |
| 2-5 | | | 100 | | | | | | Hemic Organics | |
| 5-13 | 10YR | 4/2 | 70 | 10YR | 3/6 | 30 | C | PL | Gravelly coarse sandy clay | Angular cobbles/boulders at base |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

[1] Type: C=Concentration. D=Depletion. RM=Reduced Matrix [2] Location: PL=Pore Lining. RC=Root Channel. M=Matrix

**Hydric Soil Indicators:**

- ☐ Histosol or Histel (A1)
- ☐ Histic Epipedon (A2)
- ☐ Hydrogen Sulfide (A4)
- ☐ Thick Dark Surface (A12)
- ☐ Alaska Gleyed (A13)
- ☐ Alaska Redox (A14)
- ☐ Alaska Gleyed Pores (A15)

**Indicators for Problematic Hydric Soils:[3]**

- ☐ Alaska Color Change (TA4)[4]
- ☐ Alaska Alpine swales (TA5)
- ☐ Alaska Redox With 2.5Y Hue
- ☐ Alaska Gleyed Without Hue 5Y or Redder Underlying Layer
- ☑ Other (Explain in Remarks)

[3] One indicator of hydrophytic vegetation, one primary indicator of wetland hydrology, and an appropriate landscape position must be present

[4] Give details of color change in Remarks

Restrictive Layer (if present):
Type: Rock
Depth (inches): 14

**Hydric Soil Present?** Yes ◉ No ○

Remarks:
insufficient soil carbon for redox feature development. assume hydric soils.

## HYDROLOGY

**Wetland Hydrology Indicators:**

Primary Indicators (any one is sufficient)

- ☐ Surface Water (A1)
- ☑ High Water Table (A2)
- ☑ Saturation (A3)
- ☐ Water Marks (B1)
- ☐ Sediment Deposits (B2)
- ☐ Drift Deposits (B3)
- ☐ Algal Mat or Crust (B4)
- ☐ Iron Deposits (B5)
- ☐ Surface Soil Cracks (B6)
- ☐ Inundation Visible on Aerial Imagery (B7)
- ☐ Sparsely Vegetated Concave Surface (B8)
- ☐ Marl Deposits (B15)
- ☐ Hydrogen Sulfide Odor (C1)
- ☐ Dry-Season Water Table (C2)
- ☐ Other (Explain in Remarks)

Secondary Indicators (two or more are required)

- ☐ Water Stained Leaves (B9)
- ☐ Drainage Patterns (B10)
- ☐ Oxidized Rhizospheres along Living Roots (C3)
- ☐ Presence of Reduced Iron (C4)
- ☐ Salt Deposits (C5)
- ☐ Stunted or Stressed Plants (D1)
- ☐ Geomorphic Position (D2)
- ☐ Shallow Aquitard (D3)
- ☐ Microtopographic Relief (D4)
- ☐ FAC-neutral Test (D5)

**Field Observations:**

| | | | |
|---|---|---|---|
| Surface Water Present? | Yes ○ | No ◉ | Depth (inches): |
| Water Table Present? | Yes ◉ | No ○ | Depth (inches): 5 |
| Saturation Present? (includes capillary fringe) | Yes ◉ | No ○ | Depth (inches): 5 |

**Wetland Hydrology Present?** Yes ◉ No ○

Describe Recorded Data (stream gauge, monitor well, aerial photos, previous inspection) if available:

Remarks: