WETLAND DETERMINATION DATA FORM - Alaska Region

Project/Site: Susitna-Watana Hydroelectric Project | Borough/City: Matanuska-Susitna Borough | Sampling Date: 21-Aug-15

Applicant/Owner: Alaska Energy Authority | Sampling Point: **SW15_T313_07**

Investigator(s): BAB | Landform (hillside, terrace, hummocks etc.): Toeslope

Local relief (concave, convex, none): concave | Slope: 8.7 % / 5.0 ° | Elevation:

Subregion : Cook Inlet Mountains | Lat.: | Long.: | Datum: WGS84

Soil Map Unit Name: | **NWI classification: PEM1B**

Are climatic/hydrologic conditions on the site typical for this time of year? Yes ◉ No ○ (If no, explain in Remarks.)

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ significantly disturbed? Are "Normal Circumstances" present? Yes ◉ No ○

Are Vegetation ☐ , Soil ☐ , or Hydrology ☐ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS - Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ◉ No ○	**Is the Sampled Area within a Wetland?** **Yes ◉ No ○**
Hydric Soil Present?	Yes ◉ No ○	
Wetland Hydrology Present?	Yes ◉ No ○	

Remarks:

VEGETATION - Use scientific names of plants. List all species in the plot.

	Tree Stratum	Absolute % Cover	Dominant Species?	Indicator Status
1.	Picea glauca	15	☑	FACU
2.		0	☐	
3.		0	☐	
4.		0	☐	
5.		0	☐	
	Total Cover:	15		
	Sapling/Shrub Stratum	50% of Total Cover: 7.5	20% of Total Cover: 3	
1.	Salix pulchra	4	☑	FACW
2.	Vaccinium uliginosum	3	☑	FAC
3.	Arctous ruber	3	☑	FAC
4.	Betula glandulosa	2	☐	FAC
5.	Empetrum nigrum	2	☐	FAC
6.	Salix barclayi	1	☐	FAC
7.	Salix reticulata	1	☐	FAC
8.	Picea glauca	1	☐	FACU
9.		0	☐	
10.		0	☐	
	Total Cover:	17		
	Herb Stratum	50% of Total Cover: 8.5	20% of Total Cover: 3.4	
1.	Carex aquatilis	20	☑	OBL
2.	Dodecatheon jeffreyi	4	☐	FACW
3.	Sanguisorba canadensis	3	☐	FACW
4.	Festuca altaica	2	☐	FAC
5.	Swertia perennis	2	☐	FACW
6.	Equisetum arvense	1	☐	FAC
7.	Saussurea angustifolia	1	☐	FAC
8.	Valeriana capitata	1	☐	FAC
9.	Platanthera aquilonis	0.1	☐	FACW
10.	Cornus suecica	3	☐	FAC
	Total Cover:	37.1		
	50% of Total Cover:	18.55	20% of Total Cover:	7.42

Dominance Test worksheet:

Number of Dominant Species That are OBL, FACW, or FAC: 4 (A)

Total Number of Dominant Species Across All Strata: 5 (B)

Percent of dominant Species That Are OBL, FACW, or FAC: 80.0% (A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply by:	
OBL Species	20	x 1 =	20
FACW Species	13.1	x 2 =	26.20
FAC Species	20	x 3 =	60
FACU Species	16	x 4 =	64
UPL Species	0	x 5 =	0
Column Totals:	69.1 (A)		170.2 (B)

Prevalence Index = B/A = 2.463

Hydrophytic Vegetation Indicators:

☑ Dominance Test is > 50%

☑ Prevalence Index is ≤3.0

☐ Morphological Adaptations [1] (Provide supporting data in Remarks or on a separate sheet)

☐ Problematic Hydrophytic Vegetation [1] (Explain)

[1] Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Plot size (radius, or length x width) 5m

% Cover of Wetland Bryophytes (Where applicable)

% Bare Ground 5

Total Cover of Bryophytes 65

Hydrophytic Vegetation Present? **Yes ◉ No ○**

Remarks:

SOIL

Sampling Point: SW15_T313_07

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators)

Depth (inches)	Matrix Color (moist)	Matrix %	Redox Features Color (moist)	Redox Features %	Redox Features Type[1]	Redox Features Loc[2]	Texture	Remarks
0-2							Peat	
2-4							Mucky Peat	evidence of fire and flooding
4-6							Mucky Peat	
6-7							Muck	
7-8							Muck	with gravelly sandy loam
8-12							Mucky Peat	
12-16							Muck	

[1] Type: C=Concentration. D=Depletion. RM=Reduced Matrix [2] Location: PL=Pore Lining. RC=Root Channel. M=Matrix

Hydric Soil Indicators:

- [x] Histosol or Histel (A1)
- [ ] Histic Epipedon (A2)
- [ ] Hydrogen Sulfide (A4)
- [ ] Thick Dark Surface (A12)
- [ ] Alaska Gleyed (A13)
- [ ] Alaska Redox (A14)
- [ ] Alaska Gleyed Pores (A15)

Indicators for Problematic Hydric Soils:[3]

- [ ] Alaska Color Change (TA4)[4]
- [ ] Alaska Alpine swales (TA5)
- [ ] Alaska Redox With 2.5Y Hue
- [ ] Alaska Gleyed Without Hue 5Y or Redder Underlying Layer
- [ ] Other (Explain in Remarks)

[3] One indicator of hydrophytic vegetation, one primary indicator of wetland hydrology, and an appropriate landscape position must be present

[4] Give details of color change in Remarks

Restrictive Layer (if present):
Type:
Depth (inches):

Hydric Soil Present? Yes ◉ No ○

Remarks:
Highly stratified soil with difft organic types and two horizons with mineral soil. Small angular gravels at 7". Did a lake blow out up slope?

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (any one is sufficient)

- [ ] Surface Water (A1)
- [x] High Water Table (A2)
- [x] Saturation (A3)
- [ ] Water Marks (B1)
- [ ] Sediment Deposits (B2)
- [ ] Drift Deposits (B3)
- [ ] Algal Mat or Crust (B4)
- [ ] Iron Deposits (B5)
- [ ] Surface Soil Cracks (B6)
- [ ] Inundation Visible on Aerial Imagery (B7)
- [ ] Sparsely Vegetated Concave Surface (B8)
- [ ] Marl Deposits (B15)
- [ ] Hydrogen Sulfide Odor (C1)
- [ ] Dry-Season Water Table (C2)
- [ ] Other (Explain in Remarks)

Secondary Indicators (two or more are required)

- [ ] Water Stained Leaves (B9)
- [ ] Drainage Patterns (B10)
- [ ] Oxidized Rhizospheres along Living Roots (C3)
- [ ] Presence of Reduced Iron (C4)
- [ ] Salt Deposits (C5)
- [ ] Stunted or Stressed Plants (D1)
- [ ] Geomorphic Position (D2)
- [ ] Shallow Aquitard (D3)
- [ ] Microtopographic Relief (D4)
- [x] FAC-neutral Test (D5)

Field Observations:

Surface Water Present? Yes ○ No ◉ Depth (inches):
Water Table Present? Yes ◉ No ○ Depth (inches): 5
Saturation Present? (includes capillary fringe) Yes ◉ No ○ Depth (inches): 2

Wetland Hydrology Present? Yes ◉ No ○

Describe Recorded Data (stream gauge, monitor well, aerial photos, previous inspection) if available:

Remarks: