WETLAND DETERMINATION DATA FORM - Alaska Region

Project/Site: Susitna-Watana Hydroelectric Project	В	orough/City:	Matanusk	xa-Susitna Borough Sampling Date:28-Aug-15
Applicant/Owner: Alaska Energy Authority				Sampling Point: SW15_T333_05
Investigator(s): AFW	I	_andform (hill:	side, terrac	ce, hummocks etc.): Channel (active)
Local relief (concave, convex, none): none				O ° Elevation:
Subregion : Interior Alaska Mountains	Lat.:			Long.: Datum: WGS84
Soil Map Unit Name:	_			NWI classification: R3UBH
Are climatic/hydrologic conditions on the site typical for this t	ime of year?	Yes Yes	● No ○	
		disturbed?		Normal Circumstances" present? Yes No
Are Vegetation ✓ , Soil ✓ , or Hydrology □				eded, explain any answers in Remarks.)
			•	, ,
SUMMARY OF FINDINGS - Attach site map sho		pling point	locations	s, transects, important features, etc.
Hydrophytic Vegetation Present? Yes No		1-	the Com	and ad Ave a
Hydric Soil Present? Yes ● No				npled Area /etland? Yes ◉ No ◯
Wetland Hydrology Present? Yes ● No 🤇	\supset	WI	ithin a W	/etland? Yes ● No ○
Remarks: stream channel, outflow of alpine lake. fish cove	r includes ur	ndercut banks	and overh	anging graminoids. fish observed in stream.
VEGETATION - Use scientific names of plants. L	ist all spe	cies in the	plot.	
	Absolute	Dominant	Indicator	Dominance Test worksheet:
Tree Stratum	% Cover	Species?	Status	Number of Dominant Species That are OBL, FACW, or FAC: (A)
1.				Total Number of Dominant
2	0			Species Across All Strata: 0 (B)
3				Percent of dominant Species
4				That Are OBL, FACW, or FAC: 0.0% (A/B)
5.				Prevalence Index worksheet:
Total Cover		-f T-t-1 C		Total % Cover of: Multiply by:
Sapling/Shrub Stratum 50% of Total Cover:	0 20%	or rotal Cover:	0	OBL Species 0 x1 = 0
1				FACW Species 0 x 2 = 0
2.				FAC Species 0 x 3 = 0
3				FACU Species 0 x 4 = 0
4				UPL Species <u>0</u> x 5 = <u>0</u>
5				Column Totals:0 (A)0 (B)
6.	- —			Prevalence Index = B/A = 0.000
7.				
8				Hydrophytic Vegetation Indicators: Dominance Test is > 50%
9				Prevalence Index is ≤3.0
10Total Cove	r: 0			
Herb Stratum 50% of Total Cover:		of Total Cover	: 0	Morphological Adaptations (Provide supporting data in Remarks or on a separate sheet)
1	0			✓ Problematic Hydrophytic Vegetation (Explain)
2.				¹ Indicators of hydric soil and wetland hydrology must
3.				be present, unless disturbed or problematic.
4.				Plot size (radius, or length x width)2x10 m
5	0			% Cover of Wetland Bryophytes
6				(Where applicable)
7				% Bare Ground
8				Total Cover of Bryophytes
	0			
9				
10	0			Hydrophytic
	r: 0 0	of Total Cover	0	Hydrophytic Vegetation Present? Yes No

US Army Corps of Engineers Alaska Version 2.0

SOIL Sampling Point: SW15_T333_05 Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators) **Redox Features** Depth <u>Loc</u> 2 (inches) Color (moist) Color (moist) Type ¹ ¹Type: C=Concentration, D=Depletion, RM=Reduced Matrix ² Location: PL=Pore Lining, RC=Root Channel, M=Matrix Indicators for Problematic Hydric Soils:3 **Hydric Soil Indicators:** Histosol or Histel (A1) Alaska Color Change (TA4) ☐ Alaska Gleyed Without Hue 5Y or Redder Underlying Layer Alaska Alpine swales (TA5) Histic Epipedon (A2) Alaska Redox With 2.5Y Hue ✓ Other (Explain in Remarks) Hydrogen Sulfide (A4) Thick Dark Surface (A12) ³ One indicator of hydrophytic vegetation, one primary indicator of wetland hydrology, Alaska Gleved (A13) and an appropriate landscape position must be present Alaska Redox (A14) ⁴ Give details of color change in Remarks Alaska Gleyed Pores (A15) Restrictive Layer (if present): Yes ● No ○ Type: **Hydric Soil Present?** Depth (inches): Remarks: stream channel, no soil pit, inundated **HYDROLOGY** Wetland Hydrology Indicators: Secondary Indicators (two or more are required) Primary Indicators (any one is sufficient) Water Stained Leaves (B9) ✓ Surface Water (A1) Drainage Patterns (B10) ✓ Inundation Visible on Aerial Imagery (B7) High Water Table (A2) Oxidized Rhizospheres along Living Roots (C3) Sparsely Vegetated Concave Surface (B8) Saturation (A3) Presence of Reduced Iron (C4) Marl Deposits (B15) Water Marks (B1) Salt Deposits (C5) ☐ Hydrogen Sulfide Odor (C1) Sediment Deposits (B2) Dry-Season Water Table (C2) Stunted or Stressed Plants (D1) Drift Deposits (B3) Other (Explain in Remarks) Geomorphic Position (D2) Algal Mat or Crust (B4) Shallow Aquitard (D3) Iron Deposits (B5) Microtopographic Relief (D4) Surface Soil Cracks (B6) FAC-neutral Test (D5) Field Observations: Yes ● No ○ Surface Water Present? Depth (inches): 30 Yes O No • Yes ● No ○ Water Table Present? Wetland Hydrology Present? Depth (inches): Saturation Present? Yes ○ No ● Depth (inches): (includes capillary fringe) Describe Recorded Data (stream gauge, monitor well, aerial photos, previous inspection) if available:

U.S. Army Corps of Engineers Alaska Version 2.0

Remarks: stream channel